

DR. M.T. JONES.
108 BILSTON

I.O.S.

RRS DISCOVERY

CRUISE 145

25 FEBRUARY – 24 MARCH 1984

**THE STRUCTURE OF THE UPPER OCEAN
AT THE END OF WINTER IN THE REGION
40-47°N, 13-16°W**

CRUISE REPORT NO. 166

1984

**INSTITUTE OF
OCEANOGRAPHIC
SCIENCES**

**NATURAL ENVIRONMENT
RESEARCH
COUNCIL**

INSTITUTE OF OCEANOGRAPHIC SCIENCES

Wormley, Godalming,
Surrey, GU8 5UB.
(0428 - 79 - 4141)

(Director: Dr. A.S. Laughton FRS)

Bidston Observatory,
Birkenhead,
Merseyside, L43 7RA.
(051 - 653 - 8633)

(Assistant Director: Dr D.E. Cartwright FRS)

Crossway,
Taunton,
Somerset, TA1 2DW.
(0823 - 86211)

(Assistant Director: M.J. Tucker)

When citing this document in a bibliography the reference should be given as follows:

POLLARD, R.T. *et al* 1984 RRS *Discovery* Cruise 145:
25 February - 24 March 1984. The structure of the
upper ocean at the end of winter in the region
40-47°N, 13-16°W.
Institute of Oceanographic Sciences, Cruise Report,
No. 166, 47pp.

INSTITUTE OF OCEANOGRAPHIC SCIENCES

WORMLEY

RRS DISCOVERY

Cruise 145

25 February - 24 March 1984

The structure of the upper ocean
at the end of winter in the region
40-47°N, 13-16°W

Principal Scientist

R.T. Pollard

CRUISE REPORT NO. 166

1984

| <u>CONTENTS</u> | <u>Page</u> |
|---|-------------|
| Scientific Personnel and Ships' Officers | 4 |
| Scientific Objectives | 5 |
| Narrative | 7 |
| Moorings | 10 |
| Drifting spar | 11 |
| Current meters | 14 |
| CTD casts | 14 |
| SeaSoar | 15 |
| Routine surface meteorological data and synoptic summary of weather | 18 |
| Radiosonde ascents | 21 |
| Airflow experiments | 21 |
| Ship-borne wave recorder | 23 |
| Thermosalinograph | 23 |
| Sea surface temperature/pressure fish | 24 |
| Computer | 24 |
| <u>Tables</u> | |
| 1a Mooring deployments | 26 |
| 1b Spar deployments | 26 |
| 1c Spar instrumentation | 27 |
| 2 CTD stations | 28 |
| 3 SeaSoar deployments | 29 |
| 4 SeaSoar computer run numbers | 30 |
| 5 SeaSoar survey, northern area | 32 |
| 6 SeaSoar survey, southern area | 34 |
| 7 Radiosonde ascents | 37 |
| 8 Special wind measurement runs | 38 |
| 9 Shipborne wave recorder runs | 39 |
| <u>Figures</u> | |
| 1. Cruise 145 Track plot | 40 |
| 2. Plan of North site SeaSoar survey | 41 |
| 3. Plan of South site SeaSoar survey | 42 |
| 4a. Moorings, southern site | 43 |
| 4b. Moorings, northern site | 44 |
| 5. Example of drifting spar rig | 45 |
| 6. CTD station positions | 46 |
| 7. One-minute time series of uncorrected surface meteorological observations | 47 |

SCIENTIFIC PERSONNEL

| | |
|------------------|-----------------------------------|
| R.T. Pollard | IOS (Wormley) Principal Scientist |
| S.G. Alderson | " " |
| J.W. Cherriman | " " |
| C.H. Clayson | " " |
| T.H. Guymer | " " |
| V.A. Lawford | " " |
| J.A. Moorey | " " |
| G.R.J. Phillips | " " |
| R.A. Phipps | " " |
| R.M. Sharpington | " " |
| K. Sherrocks | " " |
| J. Smithers | " " |
| P.K. Taylor | " " |
| I. Waddington | " " |

| | |
|------------------|----------------------------|
| E. Cooper | RVS (Barry) |
| Miss D. Jones | " " |
| Mrs. K.J. Thomas | Southampton University/IOS |
| R.G. Williams | University of East Anglia |

SHIP'S OFFICERS

| | |
|--------------|----------------------------|
| S.D. Mayl | Master |
| N.A. Jonas | Chief Officer |
| J.J. Price | 2nd Officer |
| P.G. Pepler | 3rd Officer |
| C.A. Langley | Radio Officer |
| R.M. Morris | Purser Catering Officer |
| I.G. McGill | Chief Engineer |
| P.J. Byrne | 2nd Engineer |
| G.L. Parker | 3rd Engineer |
| F.P. March | 4th Engineer |
| N. Davenport | 5th Engineer |
| F.P. Sharpe | Senior Electrical Engineer |

SCIENTIFIC OBJECTIVES

1. Observe the structure of the upper ocean at the end of winter at two sites with different seasonal characteristics. Observe the physical and biological changes at those sites at the start of the seasonal heating cycle.

The sites chosen were around $40^{\circ} 15'N$, $15^{\circ} 0'W$ and $45^{\circ} 45'N$, $13^{\circ} 40'W$. At the southern site the mixed layer depth was 150-200m, and the Drifting Spar moved northwards in a frontal structure at an average speed of over 14 cm/s. At the northern site the mixed layer was 250-300m deep, and the spar moved east then south at 10-15 cm/s.

2. Deploy two surface and two subsurface moorings for recovery on Cruise 146. Deploy a deepsea tide gauge for a deep water trial. Test shipborne surface meteorological instrumentation and provide surface fluxes for objective (1).

All these objectives were accomplished, but the surface and subsurface moorings set at the northern site were subsequently lost on Cruise 146. The southern toroid was recovered drifting nearly a degree south of its deployed position. The southern subsurface mooring and the tide gauge were recovered normally.

NARRATIVE

RRS Discovery sailed from Gibraltar at 1045/56 (all times GMT, day 56 = 25th February, 1984) after a two-hour delay to repair the aft crane. After a full depth calibration CTD at $37^{\circ}8'N$, $10^{\circ}58'W$ close to the 4500m depth contour, it was decided to set course directly towards $40^{\circ}N$ $15^{\circ}W$, a course which should pass through two eddies, apparent on surface temperature enhanced satellite images. (See Fig. 1 for Cruise track plot). After deep and shallow CTDs (10986/7) in the supposed centre of an eddy, the SeaSoar was deployed at 1500/58, but had to be recovered at 0300/59 to repair the propeller. The oxygen sensor was knocked off during recovery. By 0600 the SeaSoar was redeployed and towed successfully until 2000/59, during which time a routine for processing the data through to contoured sections was established.

Overnight, Aanderaa Thermistor Chains (ATCs) were calibrated by holding them, bundled up, at 50m in the mixed layer, during a CTD cast (10988). Surface and subsurface moorings and a tide gauge were deployed during daylight on day 60, after which the SeaSoar was deployed and towed continuously for 48 hours towards $47^{\circ}N$, $13^{\circ}W$. It was recovered at 2300/62, 11 n.m. short of that position after passing a suitable mooring position, and a line of CTDs (10992-4) on a near-reciprocal course was completed in time to deploy the northern subsurface mooring from 1500/63.

Further ATCs were calibrated overnight in parallel with a triangle of 2000 dbar CTDs (10996-9), one of which had to be prematurely terminated (at 1370 dbar) because of a connector failure. The northern surface toroid mooring was deployed on the afternoon of day 64, and further CTDs completed overnight while the spar was prepared. A strong easterly wind and swell prevented deployment on day 65, so a series of meteorological observations was made close to the toroid, followed by a CTD yoyo for 2.5 hours (ended again by a connector failure) and two more CTD casts overnight.

Geostrophic calculations suggested an eastward set, so the spar was deployed east of the surface and subsurface moorings at 1000/66, the swell and wind having abated a little. After steaming past the spar at several ranges to fix it and check the acoustic ranges obtainable, the SeaSoar was deployed at 1630/66 and a triangular survey relative to the drifting spar (Fig. 2) was made, yoyoing to over 350m until 0930/68. The survey consisted of an outer triangle with 24 n.m. sides, surveyed once in 24 hours, and a nested inner triangle with 12 n.m. sides, surveyed three times in a day. After a horizontal tow round the

inner triangle from 0930/68 to 1420/68, the full survey pattern was repeated, although adverse wind and swell made control of the SeaSoar difficult except on the downwind legs.

The survey finally ended and the SeaSoar was recovered at 0930/70. The spar was inspected and the rubber dinghy used to invert the pitch-roll buoy, which had overturned. After moving 6.5 n.m. upwind of the spar, a CTD cast to 1500m (11010) was made, followed by yoyoing to 60m as the ship drifted, lying to, back past the spar. After relocating the spar at 0330/71, another yoyo was begun, attempting to hold position relative to the spar. This proved difficult in the absence of a light on the spar, and by 1709/71, when the yoyo ceased, Discovery had drifted from 1500m to over 4000m away from the spar.

The yoyos had shown features extending to 600m so it was decided to attempt to find such a feature east of the spar, and do very close spaced deep CTDs across it. However, after two stations to 2000m 3 n.m. apart (11012-13), it was decided not to continue, as the feature was proving elusive, and there was concern about the increasing wind and our ability to find the spar, which had begun to drift rapidly (1 kt) southwards. Discovery therefore steamed on course 242° past the spar, locating it satisfactorily, and did a final CTD to 2000m (11014) west of it before returning to recover it at 0900/72.

After a difficult recovery in worsening seas and a wind said by the bridge to be gusting to force 10 in squalls, course was set to check the moorings before leaving the northern area. The ship was virtually hove to on passage towards the moorings, and by the time the vicinity of the toroid was reached at 1800/72 it was impossible to see it, though it was located acoustically. CTD or SeaSoar deployment was impossible, but after securing all gear, the Master was prepared to turn and run south (190°) before the wind.

Shortly before 1200/73, a sudden increase in sea surface temperature showed that we had reached the front at 43.5°N across which I wished to do a line of CTDs. The swell had lengthened enough to be reasonably comfortable, so a line of CTDs was completed (11015-11020) ending at 1600/74. The SeaSoar was then deployed running south with the wind, and towed successfully past the southern moorings, followed by a survey around them (1446/75-0508/76) to determine the structure before redeploying the spar buoy.

The tide gauge and subsurface moorings were easily located, but the acoustics on the toroid mooring had failed, and a box search failed to locate it. It was decided to continue the scientific programme, with a faint hope of coming across the toroid during our surveys (see Moorings). The spar was

redeployed very close to the subsurface mooring (1348/76), whence it drifted northwards as predicted from the preceding survey.

While the SeaSoar hydraulics were being repaired, a meteorological balloon was released, and various courses run to fix the relative positions of the subsurface mooring and spar buoys. The SeaSoar was deployed at 1730/76 but had to be recovered to remake a termination, being redeployed at 2338/76. The sea surface temperature fish was also deployed at 2354/76, long running problems with the computer logging having at last been partially resolved.

A nested triangle survey (Fig. 3) similar to that described above was run from 0012/77 to 0556/78, followed by three further circuits of the inner triangle, alternately towing as near horizontally as possible at several levels and yoyoing. The final leg was extended to the west and the SeaSoar recovered at 2140/78 to do a line of CTDs (11022-11024) back past the spar, perpendicular to the main frontal current.

The line of CTDs was terminated prematurely at 0730/79 as we were making negligible headway into an increasing wind. Instead, the SeaSoar was deployed before conditions worsened further, and towed in triangular and later diamond shaped circuits around the spar, alternately yoyoing and towing horizontally, until 1840/81. The CTD line was continued (11025-11027) from 1930/81-0223/82 and a short CTD yoyo (0600-0759/82) done near the spar before recovering it at 0847/82.

By 1003/82 the spar had been fully and smoothly recovered, and the SeaSoar was redeployed at 1036 after clearing the poop. The plan was to carry out a final survey of the northward continuation of the front. However, indicators of its position proved elusive, and a single salp fouled the conductivity sensor to the extent that the SeaSoar had to be recovered to remove it. This was done from 1653-1724/82 (a total of 30 minutes to recover and redeploy) and the survey continued for a short while, before altering course at 1930/82 towards Oporto.

A worsening westerly wind made it necessary to bring forward the recovery time of the SeaSoar to 1700/83, the PES fish having been retrieved at 1545/83. A final CTD for calibration purposes was attempted, but a connector failed with only 300m of wire out. As this was probably sufficient for calibration, all three sample bottles were fired in the mixed layer before ending the station.

Computer logging, thermosalinograph and navigation were ended at 0047/84

at 9° 07'W, and RRS Discovery entered Leixoes harbour, near Oporto, at 0740/84 to end Cruise 145.

MOORINGS (Cherriman, Waddington)

A surface and a subsurface mooring were deployed at each of the two working areas (40°N, 15°W and 46°N 13°W), four in all (Table 1). A tide gauge was also set at the southern site for IOS Bidston. The surface moorings carried meteorological packages and thermistor chains to span the mixed layer (Fig. 4). The subsurface moorings were instrumented with current meters (Fig. 4) to extend downwards the current measurements made in the surface layer from the drifting spar.

Prior to deployment, the thermistor chains were calibrated by hanging them, bundled up, at 50m in the mixed layer from the forward A frame during CTD casts. The test tapes used were immediately replayed and computer analysed. Several hardware faults were revealed by this process, demonstrating the value of shipboard processing.

The toroids were assembled on the Port side container space with a view to dropping the extension grating and deploying by just taking the weight on the crane and "walking" the toroid through the gate and over the side, the whole package being lifted at an angle to keep the crane hook well away from the anemometers etc. This worked well as both toroids were put into the water without mishap. The crane was released from the lifting strop by personnel in the rubber boat for the Southern toroid, but for the Northern one the weather was unsuitable to launch the boat, and the toroid was released by the "NO LOAD" release. Both methods were successful.

The deployments went smoothly but on the Southern toroid when the anchor was falling to the sea bed the acoustic signal made a switch (see acoustic section). The anchor appeared to bottom out normally, however, and since the toroid was still in position after 6 hrs or so, we left for the Northern area. On return 16 days later, a visual search was made for four hours, as the acoustics were likely to have failed. Although the toroid was not found, later examination of the corrected track plots revealed that we might have been searching a mile or two too far south. This highlighted the poor quality of realtime dead-reckoning. (The area was re-searched unsuccessfully on Cruise 146, but the toroid was in fact later found by chance during a SeaSoar survey drifting 53nm south of its deployed position).

The subsurface moorings were deployed from the much improved forward "A" frame anchor first without mishap.

A tide gauge was deployed successfully for Bidston from the forward crane on the Southern site.

DRIFTING SPAR (Waddington, Pollard, Phillips)

The 12 metre spar buoy and current meter string were deployed and recovered from the after deck on two occasions (Fig. 5, Table 1). Previous deployments, JASIN '78, had involved trawl winch, crane, trawling 'A' frame and ship's capstan. This equipment with the exception of the ship's capstan has been superceded by an improved lift crane, crane davit and hydraulic auxiliary winch. By utilising the auxiliary winch port wing drum and routeing a 14mm diameter polyprop tail rope around the deck sheaves a good lead was obtained through the crane davit system.

As the SeaSoar winch was located on the starboard side the spar buoy was housed on deck supports on the port side. This then meant craning the buoy from port to starboard to deploy.

Deployment 1451 on day 66 was accomplished with 5 VACMs, 4 VAEcMs and 10 kHz transponder deployed by the "anchor first" method. The current meter string was held on a stopper rope at the davit head whilst the spar buoy was transferred by crane across the deck. The buoy was then attached to the current meter string and lowered into the water on a tail rope around the capstan.

Once in the water the tail rope was paid away quickly allowing the spar to drift off from the ship for ballasting checks. Adjustment was then made by hauling the spar to the davit by capstan where a pair of annular floats could be clamped beneath the upper flange. The spar then being correctly ballasted a rope from the surface rig was led around the stern and attached to the spar bridle. The surface marker buoy (an old pitch-roll wave buoy) was then lifted into the water by crane and slipped. Backup buoys and ropes were manhandled over the stern. When all the surface rig was streaming well aft the spar buoy was lowered into the water and the tail rope cut away allowing the spar to drift clear of the ship.

The spar was recovered on day 72 in 30 kt winds and heavy seas. Pickup and recovery of the surface rig was done by grappling the rig forward and hauling the buoys by crane and capstan over the starboard stern rail. This

proved to be an awkward operation. It was hard to manhandle the floats inboard against the drag of the spar. Also, the bow propeller cut out twice causing the ship to broach to, and considerably slowing down operations.

The spar was picked up on the davit and transferred to the crane at the rail. The crane then lifted the spar so that the current meter string could be stopped off at the davit. The spar was then transferred across the deck by crane and placed into the deck supports and securely lashed down. Recovery of the current meter string then took the form of a normal mooring recovery.

From experience gained on deployment and recovery 1451, several failings in the system were apparent:

- 1) The lead from the auxiliary winch to the davit was overlong for polyprop rope. Ship's pitch caused the rope to stretch under load making current meter connections awkward. This was rectified by substituting 8mm dia. steel wire as a tail.
- 2) The stopper rope was badly sited, on the outboard davit arm, relative to the davit sheave. The stopper rope was resited on a lug immediately above the davit sheave.
- 3) The marker buoy rolled over in heavy weather and required a rubber boat trip to right it. A revised harness was made with buoys at both the spar and recovery line sides of the buoy.
- 4) The marker buoy partially flooded causing loss of ARGOS position fixes. This failure was caused by corrosion of the clamping band on the flashing light. The light housing was sealed off from the main housing on the second deployment.

Having made the above changes, the second deployment and recovery (1452) were both accomplished smoothly.

Rope harnesses and buoyancy units performed well throughout with only minor chafing at the recovery line splices.

Spar tracking

(a) VHF. Throughout both deployments the VHF transmitter worked well with ranges up to 10 miles being achieved. Accuracy of position was possible to an arc of 30° using the rotary aerial system. A particularly useful feature was the ability to determine the beam position during passes with acoustic ranging giving beam distance and VHF giving which side of the ship.

(b) Light. The flashing light beacon was not a success with flooding on the first deployment and electronic failure on the second.

(c) Acoustic. A well mixed layer 150m or more deep produces a positive sound velocity gradient and a good surface sound channel. It was thus possible to use a standard 10 kHz transponder interrogated via the PES fish to range on the drifting spar. Ranges to 8500m were obtained using various combinations of the PES beam steering facilities with beam passes reliably obtained to 5950m. Downwind courses gave the quietest conditions and hence longest ranges. In the absence of a light on the rig, several unintentionally close passes (within 600m) were made, so an early warning system was developed. Two minute dead-reckoned ship's positions were plotted once the spar came within acoustic range, and arcs drawn to establish whether the spar was off to one side. Several arcs at multiples of 1500m had to be drawn initially until the correct range became apparent. Satellite updates shift the ship's track so caused some problems. The technique saved last minute panic on a number of passes, but clearly a reliable light would have been preferable.

Near the beam pass, the range was always checked by a precise change of interrogation rate (2%) and the ambiguity of which beam the spar was on was reliably removed by the VHF direction finder.

(d) Argos. In addition to fixing the spar position by acoustic ranging, an Argos transmitter was attached to the pitchroll buoy to give extra fixes, especially when Discovery was out of acoustic range (sometimes for 12 hours or more) and to aid relocation. The Argos system tracks by satellite, recording the fixes at Toulouse in France. Using the recently installed INMARSAT communications system, the French data base could be interrogated by telex, giving the most recent fix, which might be 4 to 12 hours behind. Occasional computer problems caused loss of updates for some hours, but in general the fixes were an important aid to tracking the spar and establishing its drift. Lack of updates also signalled a problem at the spar end, when the pitchroll float had overturned.

In summary, the combination of flashing light (when it worked), VHF transmitter, Argos and acoustic fixing proved adequate to give confidence that we could relocate such a valuable free-drifting system. The redundancy was important, with two out of four devices failing on occasion. The acoustic ranges together with corrected ship's track will be used in retrospect to obtain the best possible spar track plots.

CURRENT METERS (Waddington, Clayson, Smithers, Pollard)

The VACM current meters performed well and no problems were encountered.

Four IOS vector averaging current meters were used in conjunction with five VACMs for measurements of current shear and temperature profile below the drifting spar buoy. The current meters were similar to those used since 1978 except for the temperature measuring circuits, which were increased in precision, and the sensor heads, which were enclosed in stainless steel cages to afford a limited degree of protection. Despite the latter, one head was damaged during recovery in heavy weather after the first deployment of the spar. A further head had to be replaced after this deployment due to water adsorption in the potting resin, which caused an excessive offset: this was probably due to faulty manufacture.

After each recovery, the SeaData cassettes from all current meters were processed through the SeaData Decoder, writing the decoded output onto a computer magnetic tape. The records were then fully processed on the USER computer system through to time base corrected plots of current components and temperature. A number of minor faults came to light through this process, which could be corrected before a subsequent deployment.

CTD CASTS (Smithers, Moorey, Pollard)

With one exception, all CTD casts were made with the "new" deep CTD, carrying the normal sensors and oxygen. The exception, station 10986, was done with the new shallow CTD with a 650 dbar full scale pressure sensor. This was a calibration cast before using the shallow CTD exclusively in the SeaSoar.

Calibration of the deep CTD conductivity was not straightforward, as it drifted during the cruise by an amount equivalent to about 0.03psu in salinity. There was also a depth variation amounting to about 0.005 psu change between 50 and 1000 dbar. However, bottle samples were routinely taken at 50, 200 and 2000 dbar to allow later correction. The temperatures were compared with reversing thermometer readings at 50 and 2000 dbar, and agreed within a few millidegrees on average. Oxygen samples were taken on a number of casts but correction of the CTD oxygen values was not attempted during the cruise.

In all, 5 full depth casts were made, 23 casts to 2000 dbar and several shallow yoyos (Table 2 and Fig. 6). Four stations were prematurely aborted or

delayed by cable problems, generally caused by failure of Brantner connectors.

All data were archived on the Digidata tape deck attached to the deck unit, as well as being passed to the S1 computer. In addition to a live profile plot, the data were transferred to the USER computer at the end of each cast, where they were edited and replotted, and geostrophic calculations made when appropriate.

During the cruise, programs were written for a BBC "B" microcomputer, to sample the data at about 5Hz and display a calibrated profile plot or plot against time on a monitor. The facility will be used on future cruises when the full computer system is not available.

SEASOAR (Lawford, Smithers, Pollard)

The SeaSoar was used extensively on the cruise (Tables 3,4), on passage legs and for repeated surveys in the vicinity of the drifting spar buoy (Tables 5,6 and Figs. 2,3). Indeed, it was in the water and sampling for 332.6 hours, or just under 14 days, representing 50% of the total cruise time.

On most of the runs SeaSoar was operated in its yoyo mode, oscillating from the surface to depths from 350 to 400m at a ship's speed between 7.5 and 9 knots. Oscillation period was between 10 and 14 minutes. Runs 4, 7 and 8 (Table 3) involved triangular surveys around a free floating spar buoy. On some legs of these surveys the tow speed dropped to below 4 knots due to strong headwind and sea. Control of the vehicle becomes very limited at speeds below 6 knots. On some of these legs horizontal towing was attempted, but unless the towspeed was greater than 8 knots control was very poor. However at above 8 knots $\pm 5m$ depth could be attained.

Prior to the ship leaving Gibraltar, a new hydraulic control was fitted to the SeaSoar cable capstan. Unfortunately this was irreparably damaged by a reversal of the oil flow from its supply - the aft ring main. Control of the capstan for the cruise has been via the Moog controls as on previous cruises.

At the last refit the HIAB crane normally used for launching SeaSoar had been combined with the 15 ton Crane/davit. This combination worked well and once the intricacies of the controls had been mastered it allowed adequate and safe handling of the vehicle.

However, the davit can only be manoeuvred relatively slowly, and on the first recovery, the SeaSoar was hauled clear of the water by the capstan

operator before the HIAB arm was sufficiently outboard. The SeaSoar jarred against the side of the ship, and it was found that the CTD had slid backwards in its brackets, knocking off the oxygen sensor. The sensor head was recovered, but the SeaSoar operated without oxygen for the remainder of the cruise. On subsequent recovery, the capstan was stopped while the SeaSoar was still well outboard (to prevent snatching) while the davit and arms were manoeuvred into final recovery position.

The safety of the operator when mounting and dismounting the davit was considered to be insufficient, particularly when the davit was rotated around away from the fore and aft position. Sketches are being prepared showing an extension of the operators platform which should alleviate this problem.

The new towing shoe was fitted to the aft rail of the poop deck. This guides the cable over the rail and is designed to be easily removable - two bolts only - and to leave a clear rail over which nets may be handled.

The new sheave, designed to handle the faired cable was not a success. A redesign of the sheave surface will be necessary.

At the end of Run 3 the new plastic cased Hydraulic Unit was fitted. This operated satisfactorily for the remainder of the cruise. There is however a slight oil leak from the main outer casing which made it necessary to change the oil in that compartment twice. This leak has proved difficult to stop completely.

The new towing bridle and wings have shown no sign of wear and tear. The only vehicle damage throughout the cruise was a cracked 'cowtail' at the front of the towing bridle, which had to be replaced.

After Run 8, the angle of attack of the upper tail plane was changed to about 5 degrees up in an effort to affect body pitch angle. Also a small vertical fin of 250 cm² was fitted to the top of the tail plane. These alterations both had small beneficial effects. The first did reduce the rate of change of depth of the vehicle as it started down. The fin reduced the maximum roll of the vehicle - which occurs during the upper half of the ascent - to almost a half. The SeaSoar design will be altered accordingly.

The system was deployed and recovered under quite severe conditions during this cruise. It was found best to launch the vehicle with the ship travelling downwind at 6 knots, and to recover at 4 knots also in a downwind direction. This technique had the effect of reducing the cable snatch

considerably which made for much faster and safer operations than previously. On one occasion the vehicle was recovered and redeployed with the loss of only 45 minutes of data.

SeaSoar was launched 10 times (Table 3), but had to be recovered before the planned time only 3 times. After 11 hours of the first run control of the vehicle was partially lost due to the welds on two of the impellor blades fracturing and allowing the blades to twist. Just after launching for the 6th time a cable fault developed - in the CTD circuit which became open circuit. When the vehicle was recovered a new termination was fitted to the sea cable, but further investigation showed the fault to be in a plug on the cable capstan. Just after launch on Run 9 the conductivity cell became contaminated. Recovery a few hours later showed salp firmly wrapped around the sensor head. All other recoveries were at the planned end of run.

At the start of the cruise, the new shallow CTD was calibrated with a 600m cast on the midships winch (10986, Table 2). During all SeaSoar runs, the CTD data were read into the S1 sampling computer, averaged to one value per second and calibrated. T/S curves and profiles of temperature, salinity, density, and chlorophyll were plotted every two hours on a flatbed plotter, and a live time series plot provided a check on system performance and conductivity cell fouling. The SeaSoar frequently surfaced momentarily as it turned at the top of each sawtooth, which helped to keep the sensor clean. Whenever fouling occurred, the SeaSoar was deliberately surfaced until the cell recovered its calibration. This worked on all but one occasion (Table 3).

Every two hours, the calibrated CTD data were transferred by RL01 demountable disc to the USER computer along with navigation and other data. The EM log data were integrated to give RELDIST, the distance run relative to water and RELDIST was merged with the CTD data (after further editing) using the common TIME variable. Contour plots could thus be generated with PRES and RELDIST as the independent variables. These proved invaluable in making logistic decisions, such as when to break off a survey, or which areas to resurvey.

The final data files (Table 4) were archived, and will save many man-months of effort ashore.

Triangular surveys

The SeaSoar survey pattern run around the drifting spar was arranged as two nested triangles (figs. 2 and 3). It was designed to give information on the horizontal structure of the upper ocean in the vicinity of the spar in three directions, with the inner triangle repeated about three times in a day to resolve diurnal changes, and with the outer triangle surveyed once per day to extend spatial coverage as far as possible.

The triangle was orientated such that one inner leg (C) was downwind, and the A and B legs consequently tacking with the wind 60° on either beam. The pattern was surveyed in the order ABCDE-BCAFG-CABHJ. At 8 kts, 12 n.m. sides (22 km) were chosen so that a complete survey took about a day.

The spar buoy could not, unfortunately be in the centre of the pattern because of limited acoustic ranges. It was chosen to be 1.5 n.m. from the ship at the close beam-on positions. Because navigation had to be relative to the spar, allowance was made for windage (leeway) but not current set, and turning points were determined from distance run (relative to water) measured from the ship's log. At 8 kts, turning at 10° per minute, 120° turns were begun 1.3 n.m. before the end of leg (fig. 2, detail). Whenever a beam-on acoustic range to the spar was obtained, the log value was noted and the distance run to the next turning point and along the next track recalculated, if necessary, to return to the correct tracks relative to the spar.

ROUTINE SURFACE METEOROLOGICAL DATA (Guymer, Williams, Alderson, Taylor)

a) WMO observations and synoptic summary of weather

Routine observations were made at 03, 09, 15 and 21Z, according to WMO standards and included wind speed and direction, air temperatures, sea surface temperature, pressure and visual estimates of waves and clouds. By combining these data with the observations of the bridge officers made on the main synoptic hours a 3-hourly time series was maintained. Particular attention was paid to cloud observations because these data are required for parameterising components of the surface radiation budget. The observations were useful, in conjunction with facsimile charts for giving a broad overview of the weather during the cruise.

At the beginning a ridge of high pressure extended from North Europe towards the Azores and a depression moving east along 35N gave E or NE winds as it became slow moving in the western Mediterranean. This situation was typical of the whole cruise. A blocking anticyclone centred at about 50N, 20W became established on 1 March (day 61) giving easterlies which strengthened to 30kt by 5 March (65) as a depression deepened near the Azores. A large swell originating from the Bay of Biscay was also observed. The high continued to dominate the eastern Atlantic and Europe for the next few days, intensifying and becoming centred over the UK before moving westwards on 10/11 March (70/71) and allowing a cold front to move southwards through the area early on 12th (72) bringing a change from the easterlies to strong, showery northerlies. The depression associated with the front became slow moving over northern Spain and filled only slowly, winds eventually moderating to below 15kt on 16th (76).

Increasing high cloud in the southwest and strengthening easterly winds on 17 March (77) heralded the approach of a depression from the SW. Ahead of it an occluded front moved through from the south bringing a temporary change to light southeasterlies and clear skies but, as the depression tracked NE just to the south of our position, the front moved south again and on 20th March (80) there was a change to strong NE winds with a significant drop in air temperature and humidity. This period had the highest fluxes of sensible and latent heat loss from ocean to atmosphere (in excess of 150 w m^{-2} for the total). On the 20th March (80) the synoptic pattern began to change dramatically. The block which had dominated the weather type on the cruise gave way and a mobile westerly type of flow in the NW Atlantic extended eastwards so that after calm, sunny conditions under a weak, transient ridge on 21/22 March (81/82) rough weather, preceded by a very marked long period swell prevailed as an eastwards course was set for Oporto. Generally, the wind was from between N and E throughout the cruise and the air was colder than the sea by $\sim 2^{\circ}\text{C}$. Wet-bulb depressions of $2\text{-}3^{\circ}\text{C}$ were typical and total precipitation was rather low, falling mainly as showers.

(b) Computer-logged values

One other purpose of the observations in (a) was to evaluate the performance of the shipboard automatic-logging system which recorded 1 min values of wind, pressure, dry bulb, wet bulb, hull temperature and solar radiation on the 11/34 computer. It was noticed early in the cruise that the relative wind direction was in error by about 70° on the 'plot' printout and by

55° on the dial readout. A check revealed that calibration coefficients had not been changed since Cruise 132 on which an intensive effort had been made to retrieve accurate winds so it would appear that the vane mount itself had been realigned, possibly during refit. If so this is a tedious error which means that all winds since the refit are in error, including wind speed (because of the vector addition needed to compute true wind from relative winds). It will be necessary to recompute the winds. To rectify the situation on the current cruise a constant was added to the calibration file at 0530Z Day 67 on the basis of comparisons with the special series of wind measurements also being conducted on the cruise (see p.21).

Other variables appeared to have reasonable values. Comparisons were made between the screen temperatures on the wheelhouse top, the bridge deck screens and an Assmann psychrometer and generally exhibited consistency within 0.2°C. The bridge officers had noted a discrepancy between the R.A.S.T.U.S. digital readout of air temperatures in the bridge screens and those obtained from the mercury thermometers in the same locations and therefore were using only the latter in their meteorological reports. R.A.S.T.U.S. dry bulbs were 0.4°C too low on port and 0.5°C low on starboard. Wet bulbs were 0.9°C low (port) and 1.0°C low (starboard). Our measurements confirm the wet-bulb wicks were not moistened at all during the cruise. Problems were also encountered at times from unstable R.A.S.T.U.S. readouts. The 3-hourly values on the log sheets must therefore be viewed with caution; hull temperatures logged on the computer appear reliable though they may need to be corrected to give a temperature equivalent to a bucket measurement.

A preliminary analysis of the computer-logged air temperatures shows great sensitivity to the relative wind direction; however, the variations appear to be repeatable and, given the large amount of intercomparison data plus the measurements made by extra wind sensors mounted near the thermometers it should prove possible to quantify the errors. This is particularly important if such measurements are to be used in calculating turbulent fluxes by the bulk parameterization method. Fluxes were computed in this way, using the computer-logged values, for several periods of interest and, together with radiation estimates, were compared with changes in heat content of the upper ocean. In the two detailed SeaSoar surveys, surface transfers were too small to account for the observed cooling of the water, particularly in the second where less than 10% could be accounted for. A proper evaluation of the surface flux

data must await comparison with data from the meteorological buoy and a thorough analysis of the intercomparisons made on board Discovery. Daily and weekly plots of all variables were produced on the Calcomp, and the 1-minute data for the whole cruise are reproduced in Fig. 7. They must however be used with caution in the light of the above discussion.

RADIOSONDE ASCENTS (Taylor, Thomas, Guymer)

Radiosondes using Helium filled balloons were released during the cruise in a collaborative experiment involving IOS and the Rutherford Appleton Laboratories. Each ascent was timed to coincide with an overpass of the meteorological satellites NOAA7 and NOAA8 which use Advanced Very High Resolution Radiometers (AVHRR) to provide estimates of the sea surface temperature (SST). The accuracy of the satellite SST is degraded by uncertainty in estimating the amount of atmospheric water vapour and by failure to entirely eliminate cloud contaminated data. The water vapour measurements provided by the radiosondes will be used, together with the SST measurements obtained during this cruise, to quantify the errors in the satellite SST values and to evaluate alternative satellite data retrieval schemes.

Of the 28 radiosonde ascents (Table 7), 22 were timed to be coincident with NOAA7 overflights since this satellite carries a 'split-window' AVHRR, that is one having two channels in the same transmission/^{window}thus allowing more accurate water vapour correction. 16 ascents were conducted in daylight to allow evaluation of cloud clearance techniques using the visible wavelength AVHRR channel. Ascents were only conducted for overpasses if less than 6 eighths total cloud cover was expected.

It is expected that the detailed satellite SST data obtained as part of this experiment will also be of value for defining the horizontal extent of SST features associated with the oceanic mixed layer structures studied during the cruise.

AIRFLOW EXPERIMENTS (Taylor, Guymer, Thomas)

Estimation of the fluxes of momentum, sensible heat and latent heat between the sea and the air using the bulk aerodynamic formulae requires accurate measurements of the mean wind, air temperature and humidity. For the greatest accuracy it is necessary to adjust the measurements to take into

account the height of the instruments and this correction is a function of stability. However, it is well known that the presence of the ship disturbs the airflow causing uncertainty with regard to the true height to which the measurements refer and often causing the exposure of the instrument to be far from ideal. For climate research and for the calibration of oceanographic satellites there is a need for more accurate flux estimates than hitherto, and it was therefore decided to investigate the effect of airflow disturbance on the routine meteorological measurements logged by the computer system on RRS Discovery.

Anemometers and wind vanes were mounted in the following positions:-

- (a) 4m above and 0.5m forward of the front edge of the foremast platform midway between the mast and the ship's port anemometer.
- (b) above the port and starboard thermometer screens on the wheelhouse top ('Monkey Island'). A vane at about 1.0m and anemometer 0.5m above each screen.
- (c) a further anemometer 2.65m above the port wheelhouse top screen.
- (d) above the starboard bridge deck screen, an anemometer at 0.8m and wind vane at 0.4m above the screen top.

Data from these instruments were recorded on a Microdata logger at one minute intervals throughout the cruise. Variations of the wind between the different positions will be correlated with changes in relative wind, and differences between the port and starboard computer logged dry bulb and wet bulb depression values. For these comparisons the readings of the foremast anemometer will be used as a standard, an estimate of the error in this will be made using comparisons with the data from the surface mooring.

Measurements of the windflow in the region of the bow were made with additional anemometers mounted on a horizontal pole at distances either of 4m and 2m, or at 5m and 3m forwards of the bow. In each case a wind vane was mounted 1m inboard of the aft anemometer. Readings were taken for varying relative winds by noting the 1 minute averaged values on the display of the Portalogger data recording units (Table 8). A separate series of measurements was made with the pole mounted vertically in the bow. In this case the anemometers were at 4.8m and 1.8m above the bow plate with a wind vane midway between them. 1.4m standoff arms were used to place the instruments approximately 0.4m forward of the bow. Unfortunately this series of readings was terminated when, during a squall, a wave broke over the bow and broke the lashings of the Portalogger units. The loggers were swept into the anchor

machinery and suffered mechanical damage.

In order to visualise the flow over the bow, foredeck and ship's superstructure, a series of six smoke flares were ignited and photographs taken of the smoke stream from different angles. These experiments clearly indicated that, for the relative wind on the ship's bow, the air reaching the wheelhouse top screens may have originated from a level at or below the top of the bow.

SHIP-BORNE WAVE RECORDER (Guymer, Thomas)

The wave-recorder was operated on many occasions during the cruise (see Table 9) although on some of these the vessel was steaming. Maximum wave heights were about 7.5m crest-to-trough. These data will be of use in describing the general sea-state conditions which prevailed and in studies relating to possible sea-state dependence of coefficients in the bulk parameterization of surface turbulent fluxes. However, use of the SBWR is not facilitated by its cramped position behind the gravimeter which makes it difficult to annotate and change the chart. Also, while there is provision to link the SBWR to the ship's computer this has not so far been done. In view of the increasing interest in instrumentally-obtained wave records for the purpose of validating satellite microwave measurements of wave-height and wave-length, it is highly desirable that the SBWR facility on Discovery should be exploited to the full.

THERMOSALINOGRAPH (Cooper, Phipps)

Throughout the cruise, the temperature at the non-toxic intake and the salinity of the non-toxic supply were monitored with a Plessey Thermosalinograph sampling every ten seconds. Only one of the pumps driving the non-toxic supply is operational, and there have been several minor leaks in the pipework.

A requirement to log salinity to three decimal places required modification to the sampling program at the start of the cruise, and a constant salinity offset was applied to bring the computer logged value to approximately the right calibrated value. Bottle samples were tapped off the supply every 2 or 4 hours during SeaSoar surveys to allow later calibration.

SEA SURFACE TEMPERATURE/PRESSURE FISH (Lawford, Clayson, Cooper, Jones)

Considerable trouble was experienced in computer logging of the SST fish through the FM interface. These unfortunately precluded its use during the northern survey, but logging of the temperature-only fish was eventually achieved.

In retrospect, the primary problem was that changes to the sampling programs necessitated by the change to a 20K executive on cruise 132 had not been completed nor documented. Attempting to start sampling before the most recent software was in use resulted in four crashes of the S1 computer. Care had been taken to avoid periods of CTD or SeaSoar logging, so only about ten minutes of navigation and thermosalinograph data were lost on each occasion.

The new pressure/temperature fish had not been completed at the start of the cruise, and the electronics were found not to fit the housing. The temperature-only fish could be used, however, and worked satisfactorily during the second spar deployment (at the south site) until cable damage caused progressive failure. After the cable termination had been repaired, the fish was redeployed for a short time during the final SeaSoar front survey period.

COMPUTER (Cooper, Jones, Pollard)

The S1 computer sampled continuously throughout the cruise apart from the short crashes mentioned above. The USER system worked continuously with no crashes.

In addition to the usual navigational and meteorological data logging, a Plessey thermosalinograph, a Neil Brown CTD, a Batfish and, eventually, a Sea-surface temperature fish were also logged by the S1 computer.

During normal operation, the S1 copes very well, the 'shuffler' being idle for most of the time, except when large coreloads such as PIP and RTL are used. Their use invokes the shuffler, causing occasional data loss when the raw sampling programs can't get enough processor time. When the FM interface is being sampled however, the system's response is noticeably slower, so careful consideration should be given to the advisability of sampling two FM interfaces concurrently.

Nearly all data were transferred to the USER system and extensively processed as described elsewhere. In particular, several tasks previously done

by the S1 system were transferred to the PSTAR applications suite on the USER system, which was more versatile and relieved the load on the S1. PNEWDR and PEDSAT replaced the old S1 EDTNAV program, allowing corrected navigation to be recalculated several times if necessary.

Externally logged data from various instruments such as current meters, VACMs and thermistor chain loggers were also processed on the USER system. Also, the bathymetry in corrected meters (Carter's corrections) was typed into the system.

The hardware functioned with only minor troubles throughout the cruise. The only system to cause concern was the HP2100 Satellite Navigation computer. This was temperamental at the start of the cruise, but once the connectors were cleaned, it gave no further problems.

A small data loss was caused by a malfunction of the thermosalinograph chart recorder, otherwise, the integrity of the data has been maintained.

Table 1a

Mooring deployments

| Station | Mooring number | Type | Deployment day/time | Latitude °N | Longitude °W | Depth corr.m |
|---------|----------------|------------|---------------------|-------------|--------------|--------------|
| 10989 | 368 | toroid | 60/1300 | 40° 20.02 | 15° 01.37 | 5365 |
| 10990 | 369 | subsurface | 60/1852 | 40° 15.36 | 15° 02.45 | 5365 |
| 10991 | | tide gauge | 60/2230 | 40° 17.52 | 15° 03.30 | 5362 |
| 10995 | 370 | subsurface | 63/1830 | 45° 43.76 | 13° 46.25 | 4825 |
| 11000 | 371 | toroid | 64/1930 | 45° 49.00 | 13° 39.00 | 4823 |

Table 1b

Spar deployments

| Station | Deployment number | Set/recover | Day/time | Latitude (N) | Longitude (W) | Duration |
|---------|-------------------|-------------|----------|--------------|---------------|----------|
| 11006 | 1451 | S | 66/1312 | 45° 49.6 | 13° 29.8 | 5d 20h |
| | | R | 72/0858 | 45° 30.9 | 12° 59.9 | |
| 11021 | 1452 | S | 76/1350 | 40° 15.5 | 15° 01.2 | 5d 19h |
| | | R | 82/0847 | 40° 53.0 | 14° 57.0 | |

Table 1c

Spar instrumentation

| <u>Deployment 1451</u> | | | <u>Deployment 1452</u> | | |
|------------------------|--------|-----------|------------------------|--------|-----------|
| Instrument | Number | Depth (m) | Instrument | Number | Depth (m) |
| VACM | 627 | 15 | VACM | 629 | 20 |
| VAECM | 1 | 25 | VAECM | 2 | 48 |
| VAECM | 4 | 35 | VAECM | 3 | 76 |
| VACM | 668 | 45 | VACM | 429 | 96 |
| VAECM | 3 | 65 | TXP | | 105 |
| VACM | 673 | 85 | VAECM | 4 | 115 |
| VAECM | 2 | 105 | VAECM | 1 | 135 |
| VACM | 429 | 125 | VACM | 627 | 155 |
| VACM | 629 | 145 | VACM | 673 | 175 |
| TXP | | 195 | VACM | 668 | 195 |

Table 2
CTD Stations

| Number | Day/Time | Lat. (N) | Long. (W) | Depth | Notes |
|--------|----------|----------|-----------|-------|--|
| 10985 | 57/2207 | 37 08.5 | 10 58.4 | 4671 | Calibration cast |
| 10986 | 58/0651 | 37 30.1 | 11 32.0 | 600 | Calib. of shallow CTD |
| 10987 | 58/1031 | 37 32.7 | 11 32.2 | 5188 | In eddy near 10986 |
| 10988 | 60/0110 | 40 14.5 | 15 00.4 | 5400 | Near S moorings |
| 10992 | 63/0043 | 46 52.7 | 13 03.4 | 2000 | Triangular survey |
| 10993 | 63/0552 | 46 29.9 | 13 14.7 | 2000 | north of north |
| 10994 | 63/1332 | 45 41.6 | 13 43.9 | 2030 | moorings |
| 10996 | 63/2230 | 46 00.8 | 14 05.1 | 2000 | " |
| 10997 | 64/0244 | 46 19.4 | 14 28.8 | 1370 | " (cable fault) |
| 10998 | 64/0704 | 46 24.3 | 13 51.9 | 2000 | " |
| 10999 | 64/1140 | 46 05.2 | 13 32.0 | 2000 | " |
| 11001 | 65/0315 | 45 27.9 | 13 16.0 | 2041 | Dogleg SE of N mooring |
| 11002 | 65/0740 | 45 07.1 | 13 35.2 | 1550 | " (cable fault) |
| 11003 | 65/1926 | 45 48.6 | 13 39.0 | 400 | Yoyos keeping station |
| to | 65/2104 | 45 49.3 | 13 39.5 | yoyo | by north toroid |
| 11004 | 65/2303 | 45 53.7 | 13 38.5 | 2000 | Between 10994 and 999 |
| 11005 | 66/0455 | 45 45.2 | 13 07.2 | 2000 | Course 112 from 11004 |
| 11007 | 70/1358 | 45 47.0 | 12 56.5 | 1500 | East of spar |
| 11008 | 70/1426 | 45 47.0 | 12 56.3 | 600 | Yoyos drifting past |
| to | 71/0122 | 45 44.1 | 13 06.8 | yoyo | spar |
| 11009 | 71/0336 | 45 42.3 | 13 02.4 | 600 | Yoyos keeping station |
| to | 71/0722 | 45 41.1 | 13 01.6 | yoyo | by spar |
| 11010 | 71/0800 | 45 40.9 | 13 01.4 | 2000 | Deep cast by spar |
| 11011 | 71/0829 | 45 40.9 | 13 01.4 | 600 | Yoyos keeping station |
| to | 71/1730 | 45 40.0 | 13 00.2 | yoyo | fairly near spar |
| 11012 | 71/2158 | 45 41.8 | 12 42.1 | 2000 | East of spar |
| 11013 | 72/0011 | 45 39.0 | 12 45.3 | 2000 | ditto |
| 11014 | 72/0423 | 45 26.4 | 13 16.6 | 2000 | West of spar |
| 11015 | 73/1243 | 43 21.3 | 14 19.8 | 2000 | Line of CTDs across |
| 11016 | 73/1649 | 43 29.6 | 14 16.9 | 2000 | outcrop of |
| 11017 | 73/2213 | 43 37.4 | 14 15.0 | 4511 | 12 deg. (to bottom) |
| 11018 | 74/0304 | 43 45.7 | 14 05.0 | 2000 | isotherm |
| 11019 | 74/0641 | 43 53.6 | 13 58.4 | 2000 | " |
| 11020 | 74/1414 | 43 11.7 | 14 25.0 | 5356 | " (to bottom) |
| 11022 | 78/2245 | 40 43.1 | 15 14.8 | 2000 | Line of CTDs along |
| 11023 | 79/0144 | 40 41.1 | 15 05.2 | 2000 | 110 line past spar |
| 11024 | 79/0643 | 40 39.8 | 14 50.9 | 2000 | " |
| 11025 | 81/2008 | 40 49.9 | 14 56.2 | 2000 | Second line as above |
| 11026 | 81/2254 | 40 47.5 | 14 46.9 | 2000 | " |
| 11027 | 82/0132 | 40 45.4 | 14 36.0 | 2050 | " |
| 11028 | 82/0600 | 40 51.7 | 14 57.0 | 300 | Yoyo close to spar |
| to | 82/0759 | 40 51.6 | 14 57.3 | yoyo | |
| 11029 | 83/1750 | 41 07.3 | 10 27.8 | 300 | Final calib. cast, ended by cable fault |

Table 3
SeaSoar Deployments

| Run No. | Day/Time in | Day/Time out | Duration (hrs) | Type of Run | Reason Out |
|---------|-------------|--------------|----------------|---|---|
| 1 | 58/1510 | 59/0230 | 11.3 | Yoyo to 350m. 8 knots. Passage leg. | Partial loss of control due to the weld on two of the impellor blades cracking. |
| 2 | 59/0600 | 59/2200 | 14.0 | Yoyo to 350m. 8 knots. Passage leg. | End of run. |
| 3 | 60/2330 | 62/2300 | 47.5 | Yoyo to 375 m. 8-9 knots. Passage leg and survey. | End of run. |
| 4 | 66/1650 | 70/0930 | 88.7 | Yoyo around triangles and some horizontal tows. Generally low speed 4-8 knots. | End of run. |
| 5 | 74/1630 | 76/0510 | 36.7 | Yoyo to 400m. 8-9 knots. Passage leg. | End of run. |
| 6 | 76/1730 | 76/1930 | 2.0 | | Cable fault. Eventually found to be at capstan. |
| 7 | 76/2340 | 78/2120 | 45.7 | Yoyo to 390m. and short horizontal tows around triangle. | End of run. |
| 8 | 79/0920 | 81/1820 | 57.0 | Yoyo to 390m. and short horizontal tows around triangle. | End of run. |
| 9 | 82/1050 | 82/1650 | 6.0 | Yoyo to 380m. - across front. | Conductivity probe contaminated. Cured by removal of salp. |
| 10 | 82/1720 | 83/1700 | 23.7 | Yoyo to 360m. 8-9 knots. Passage leg. | End of run. |

Table 4

SeaSoar computer run numbers

| Run SS1450-- | Day/Time | | Distance Run (km) | | Comments |
|-----------------|--|---------|-------------------|--------|----------------|
| | Start | End | Start | End | |
| | On passage from 35° 34N 11° 32W to 40° 10N 15° 00W | | | | |
| 01 | 58/1331 | 58/1900 | 592.8 | 653.6 | |
| 02 | 58/1827 | 58/2302 | 645.2 | 715.2 | |
| 03 | 58/2218 | 59/0240 | 704.9 | 766.2 | |
| 04 | 59/0240 | 59/0958 | 766.2 | 836.3 | |
| 05 | 59/0911 | 59/1344 | 824.2 | 895.9 | |
| 06 | 59/1305 | 59/1736 | 885.5 | 955.8 | |
| 07 | 59/1621 | 59/2158 | 945.1 | 1021.2 | |
| | On passage from 40° 17N 15° 03W to 46° 51N 13° 04W | | | | |
| 08 | 60/2216 | 61/0400 | 1120.9 | 1189.8 | |
| 09 | 61/0330 | 61/0742 | 1175.7 | 1246.0 | |
| 10 | 61/0700 | 61/1130 | 1235.7 | 1305.1 | |
| 11 | 61/1051 | 61/1517 | 1294.9 | 1365.1 | |
| 12 | 61/1441 | 61/1900 | 1355.3 | 1425.1 | |
| 13 | 61/1824 | 61/2234 | 1415.2 | 1485.2 | |
| 14 | 61/2158 | 62/0200 | 1475.2 | 1545.1 | |
| 15 | 62/0125 | 62/0533 | 1534.8 | 1605.8 | |
| 16 | 62/0452 | 62/0922 | 1595.0 | 1666.0 | |
| 17 | 62/0841 | 62/1309 | 1655.7 | 1725.4 | |
| 18 | 62/1232 | 62/1700 | 1715.4 | 1785.4 | |
| 19 | 62/1600 | 62/2100 | 1770.4 | 1843.4 | |
| 20 | 62/2033 | 62/2300 | 1835.0 | 1871.3 | |
| | Triangular survey, north site | | | | |
| 21 | 66/1644 | 66/2150 | 2634.9 | 2705.1 | A1,B1,C1 |
| 22 | 66/2116 | 67/0234 | 2695.7 | 2766.0 | C1,D1,E1,B2 |
| 23 | 67/0128 | 67/0700 | 2755.0 | 2826.2 | B2,C2,A2 |
| 24 | 67/0607 | 67/1138 | 2815.0 | 2885.6 | A2,F1,G1,C3 |
| 25 | 67/1058 | 67/1626 | 2875.0 | 2945.8 | C3,A3,B3,H1 |
| 26 | 67/1542 | 67/2037 | 2934.9 | 3005.0 | B3,H1,J1,A4,B4 |
| 27 | 67/1948 | 68/0052 | 2994.7 | 3065.1 | B4,C4,D2,E2 |
| 28 | 68/0012 | 68/0556 | 3054.9 | 3125.0 | E2,B5,C5 |
| 29 | 68/0507 | 68/0940 | 3115.0 | 3177.0 | C5,A5,B6,C6 |
| 30 | 68/0940 | 68/1420 | 3177.0 | 3241.0 | C6,A6,B7 |
| 31 | 68/1420 | 68/1916 | 3241.0 | 3305.0 | B7,C7,A7 |
| 32 | 68/1823 | 69/0023 | 3294.9 | 3365.4 | A7,F2,G2,C8 |
| 33 | 68/2343 | 69/0541 | 3355.2 | 3425.3 | C8,A8,B8,H2 |
| 34 | 69/0500 | 69/1016 | 3414.9 | 3485.2 | H2,J2,A9 |
| 35 | 69/0923 | 69/1510 | 3475.2 | 3547.7 | A9,B9,C9,D3 |
| 36 | 69/1510 | 69/1720 | 3547.7 | 3567.0 | E3,HORIZ |
| 37 | 69/1700 | 69/2007 | 3535.1 | 3605.1 | B10,C10 |
| 38 | 69/1928 | 70/0032 | 3594.8 | 3665.7 | C10,A10,B11,H3 |
| 39 | 69/2353 | 70/0438 | 3655.2 | 3725.0 | H3,J3,A11 |
| 40 | 70/0353 | 70/0900 | 3715.3 | 3785.0 | A11,B12,C11 |
| 41 | 70/0801 | 70/0940 | 3775.0 | 3791.7 | |

SeaSoar computer run numbers
Table 4 cont.

| Run | Day/Time | | Distance Run (km) | | Comments |
|----------|---|---------|-------------------|--------|------------------------------|
| SS1450-- | Start | End | Start | End | |
| | On passage from 43° 9' N 14° 27' W to 40° 0' N 14° 45' W | | | | |
| 42 | 74/1654 | 74/2116 | 4556.2 | 4625.1 | |
| 43 | 74/2038 | 75/0100 | 4615.4 | 4684.2 | |
| 44 | 75/0023 | 75/0447 | 4675.1 | 4745.1 | |
| 45 | 75/0409 | 75/0833 | 4734.9 | 4805.2 | |
| 46 | 75/0754 | 75/1210 | 4794.6 | 4865.3 | |
| 47 | 75/1134 | 75/1603 | 4855.2 | 4925.3 | |
| 48 | 75/1520 | 75/2015 | 4915.2 | 4985.0 | |
| 49 | 76/1932 | 86/0043 | 4974.9 | 5045.9 | |
| 50 | 76/0001 | 76/0449 | 5035.8 | 5105.2 | |
| 51 | 76/1708 | 76/0505 | 5095.1 | 5109.0 | |
| | Triangular survey, south site | | | | |
| 52 | 76/1746 | 77/0141 | 5205.0 | 5275.3 | A1 |
| 53 | 77/0100 | 77/0537 | 5264.7 | 5335.0 | A1,B1,C1 |
| 54 | 77/0455 | 77/0924 | 5324.7 | 5395.4 | C1,D1,E1 |
| 55 | 77/0847 | 77/1204 | 5385.3 | 5455.6 | E1,B2,C2,A2 |
| 56 | 77/1237 | 77/1700 | 5445.7 | 5513.6 | A2,F1,G1 |
| 57 | 77/1629 | 77/2100 | 5505.5 | 5575.1 | G1,C3,A3,B3 |
| 58 | 77/2105 | 78/0055 | 5542.8 | 5624.3 | B3,H1,J1 |
| 59 | 78/0055 | 78/0540 | 5624.3 | 5687.0 | H*:A4,B4,C4 |
| 60 | 78/0556 | 78/1031 | 5691.1 | 5756.8 | A5,B5,C5 |
| 61 | 78/1030 | 78/1500 | 5756.8 | 5825.4 | H*:A6,B6,C6 |
| 62 | 78/1450 | 78/2133 | 5822.8 | 5924.4 | A7,B7,C7,A8 |
| | Continuation of south site survey | | | | |
| 63 | 79/0907 | 79/1100 | 5984.5 | 6010.4 | A9,B9 |
| 64 | 79/1100 | 79/1700 | 6010.4 | 6081.5 | H*:B9,C9,A10 |
| 65 | 79/1550 | 79/1900 | 6062.9 | 6109.3 | A10,B10 |
| 66 | 79/1900 | 79/2135 | 6109.3 | 6122.9 | H*:B10 |
| 67 | 79/2135 | 80/0035 | 6126.1 | 6161.7 | C10 |
| 68 | 80/0035 | 80/0640 | 6161.7 | 6242.5 | H*:A11,B11,C11 yoyo A12 |
| 69 | 80/0640 | 80/1203 | 6242.5 | 6310.0 | B12,H2,J2 |
| 70 | 80/1157 | 80/1339 | 6300.0 | 6334.2 | A13 |
| 71 | 80/1339 | 80/1945 | 6334.2 | 6415.5 | H*:B13,H3,J3,A14 |
| 72 | 80/1945 | 81/0112 | 6415.5 | 6486.2 | B14,H4,J4 |
| 73 | 81/0112 | 81/0920 | 6486.2 | 6600.0 | H*:A15,B15,H5,J5, A16,B16 |
| 74 | 81/0933 | 81/1428 | 6600.0 | 6670.3 | B16,C12,A17,B17 |
| 75 | 81/1351 | 81/1830 | 6660.3 | 6725.9 | B17,H6,J6 |
| | On passage from 40° 52' N 14° 58' W to 41° 6' N 10° 31' W | | | | |
| 76 | 82/1036 | 82/1454 | 6832.2 | 6895.7 | |
| 77 | 82/1412 | 82/1900 | 6885.8 | 6953.7 | |
| 78 | 82/1830 | 82/2300 | 6945.7 | 7019.4 | |
| 79 | 82/2211 | 83/0224 | 7005.8 | 7075.3 | |
| 80 | 83/0149 | 83/0607 | 7065.8 | 7135.3 | |
| 81 | 83/0530 | 83/0955 | 7125.0 | 7195.0 | |
| 82 | 83/0920 | 83/1352 | 7185.9 | 7255.2 | |
| 83 | 83/1313 | 83/1700 | 7245.6 | 7298.9 | |

*Note: H: means Horizontal.

Table 5

SeaSoar survey, Northern area

| Run | Day | Start Time | End Time | Leg/Course | Start Reldist |
|-----|-----|------------|----------|------------|---------------|
| 21 | 66 | 1756 | 1937 | A1/150 | 2651 |
| | | 1948 | 2114 | B1/030 | 2674 |
| 22 | | 2126 | 2239 | C1/270 | 2697 |
| | | 2246 | 0006 | D1/210 | 2719 |
| 23 | 67 | 0017 | 0219 | E1/090 | 2742 |
| | | 0224 | 0400 | B2 | 2763 |
| | | 0412 | 0520 | C2 | 2786 |
| 24 | | 0532 | 0712 | A2 | 2805 |
| | | 0718 | 0920 | F1/090 | 2829 |
| | | 0931 | 1048 | G1/330 | 2851 |
| 25 | | 1054 | 1208 | C3 | 2873 |
| | | 1218 | 1356 | A3 | 2894 |
| 26 | | 1407 | 1546 | B3 | 2915 |
| | | 1552 | 1710 | H1/330 | 2935 |
| | | 1722 | 1839 | J1/210 | 2959 |
| | | 1845 | 2039 | A4 | 2982 |
| 27 | | 2050 | 2252 | B4 | 3006 |
| | | 2304 | 2325 | C4 | 3035 |
| | | 2325* | 2353* | C4/255 | 3043 |
| | | 2353 | 0021 | C4/270 | 3052 |
| 28 | 68 | 0026 | 0204 | D2 | 3060 |
| | | 0216 | 0417 | E2 | 3084 |
| 29 | | 0424 | 0602 | B5 | 3107 |
| | | 0615 | 0727 | C5 | 3127 |
| | | 0740 | 0928 | A5 | 3150 |

* course adjustment as too far N

Table 5 cont.

| Run | Day | Start Time | End Time | Leg/Course | Start Reldist |
|--------|-----|------------|----------|------------|---------------|
| 30 | | 0939 | 1059 | B6 | 3175 |
| | | 1111 | 1226 | C6 | 3197 |
| | | 1239 | 1416 | A6 | 3220 |
| 31 | | 1428 | 1604 | B7 | 3240 |
| | | 1616 | 1725 | C7 | 3262 |
| 32 | | 1738 | 1927 | A7 | 3284 |
| | | 1935 | 2154 | F2 | 3307 |
| | | 2207 | 2330 | G2 | 3330 |
| 33 | | 2336 | 0045 | C8 | 3353 |
| | 69 | 0058 | 0228 | A8 | 3372 |
| | | 0239 | 0446 | B8 | 3391 |
| 34 | | 0454 | 0616 | H2 | 3413 |
| | | 0629 | 0748 | J2 | 3435 |
| 35 | | 0756 | 0951 | A9 | 3458 |
| | | 1003 | 1136 | B9 | 3481 |
| | | 1148 | 1255 | C9 | 3502 |
| | | 1301 | 1435 | D3 | 3522 |
| 36, 37 | | 1447 | 1710 | E3 | 3544 |
| | | 1715 | 1859 | B10 | 3565 |
| 38 | | 1912 | 2021 | C10 | 3588 |
| | 69 | 2033 | 2211 | A10 | 3611 |
| | | 2222 | 2352 | B11 | 3634 |
| 39 | | 2358 | 0111 | H3 | 3655 |
| | 70 | 0124 | 0240 | J3 | 3678 |
| 40 | | 0247 | 0440 | A11 | 3700 |
| | | 0452 | 0617 | B12 | 3727 |
| | | 0629 | 0739 | C11 | 3751 |
| 41 | | | end | 3770 | |

Table 6

SeaSoar survey, Southern area

| Run | Day | Start | End | Leg/Course | Start Reidist | Comments |
|-----|-----|-------|------|------------|------------------|----------|
| 55 | 77 | 0013 | 0105 | C0/050 | 5253 | |
| 53 | | 0116 | 9248 | A1/290 | 5267 | |
| | | 0259 | 0427 | B1/170 | 5294 | |
| 54 | | 0439 | 0602 | C1/050 | 5320 | |
| | | 0608 | 0739 | D1/350 | 5342 | |
| 55 | | 0754 | 0921 | E1/230 | 5368 | |
| | | 0927 | 1047 | B2 | 5395 | |
| | | 1049 | 1237 | C2 | 5419 | |
| 56 | | 1249 | 1416 | A2 | 5447 | |
| | | 1422 | 1531 | F1/230 | 5471 | |
| 57 | | 1542 | 1713 | G1/110 | 5492 | |
| | | 1719 | 1838 | C3 | 5517 | |
| | | 1848 | 2009 | A3 | 5538 | |
| 58 | | 2021 | 2141 | B3 | 5565 | |
| | | 2147 | 2331 | H1/110 | 5585 | |
| | 78 | 2343 | 0055 | J1/350 | 5607 | |
| 59 | | 0101 | 0204 | A4 | 5626 | |
| | | 0220 | 0403 | B4 | 5645 | |
| | | 0415 | 0540 | C4 | 5666 | |
| 60 | | 0556 | 0715 | A5 | 5688 | Horiz |
| | | 0729 | 0852 | B5 | 5713 | Horiz |
| | | 0904 | 1026 | C5 | 5735 | Horiz |
| 61 | | 1038 | 1154 | A6 | 5757 | |
| | | 1206 | 1322 | B6 | 5781 | |
| | | 1334 | 1448 | C6 | 5802 | |
| 62 | | 1459 | 1604 | A7 | 5823 | Horiz |
| | | 1617 | 1736 | B7 | 5844 | Horiz |

Table 6 cont.

| Run | Day | Start | End | Leg/Course | Start Releast | Comments |
|-----|-----|-------|------|------------|------------------|----------------|
| | | 1748 | 1904 | C7 | 5866 | Horiz |
| | | 1917 | 2118 | A8 | 5886 | |
| | | | | end | 5925 | |
| | | | (CTD | Survey) | | |
| | 79 | | | | | |
| 63 | | 0923 | 1042 | A9 | 5985 | |
| 64 | | 1054 | 1312 | B9 | 6009 | |
| | | 1327 | 1549 | C9 | 6037 | |
| 65 | | 1601 | 1720 | A10 | 6064 | Yoyo |
| | | 1726 | 1855 | B10 | 6087 | Yoyo |
| 66 | | | 2120 | | 6110 | Engine Failure |
| 67 | 80 | 2142 | 0035 | C10 | 6126 | Yoyo |
| 68 | | 0043 | 0157 | A11 | 6162 | Horiz |
| | | 0209 | 0321 | B11 | 6184 | Horiz |
| | | 0333 | 0523 | C11 | 6206 | Horiz |
| | | 0541 | 0640 | A12 | 6225 | Yoyo |
| 69 | 80 | 0653 | 0809 | B12 | 6245 | Yoyo |
| | | 0816 | 0955 | H2 | 6268 | Yoyo |
| | | 1006 | 1155 | J2 | 6289 | Yoyo |
| 70 | | 1204 | 1327 | A13 | 6309 | Yoyo |
| 71 | | 1335 | 1453 | B13 | 6332 | Horiz |
| | | 1500 | 1630 | H3 | 6353 | Horiz |
| | | 1642 | 1825 | J3 | 6377 | Horiz |
| | | 1835 | 1945 | A14 | 6397 | Horiz |
| 72 | | 1959 | 2112 | B14 | 6420 | Yoyo |
| | | 2120 | 2252 | H4 | 6440 | Yoyo |
| | 81 | 2304 | 0100 | J4 | 6462 | Yoyo |
| 73 | | 0107 | 0224 | A15 | 6484 | Horiz |
| | | 0236 | 0352 | B15 | 6506 | Horiz |
| | | 0400 | 0525 | H5 | 6527 | Horiz |

Table 6 cont.

| Run | Day | Start | End | Leg/Course | Start Releast | Comments |
|-----|-----|-------|------|------------|------------------|----------|
| | | 0535 | 0716 | J5 | 6549 | Horiz |
| | | 0727 | 0842 | A16 | 6573 | Horiz |
| 74 | | 0856 | 1011 | B16 | 6594 | Horiz, |
| | | | | | 6604 | Yoyo |
| | | 1024 | 1212 | C12 | 6615 | Yoyo |
| | | 1225 | 1353 | A17 | 6638 | Yoyo |
| 75 | | 1406 | 1522 | B17 | 6661 | Yoyo |
| | | 1527 | 1647 | H6 | 6685 | Yoyo |
| | | 1658 | 1842 | J6 | 6706 | Yoyo |
| | | | | end | 6722 | |

Table 7
Radiosonde Ascents

| Ascent No. | Jday | Time Z | Lat N | Long W | Satellite Orbit | Satellite Time | Comment |
|------------|------|--------|-------|--------|-----------------|----------------|---------|
| 145D-001 | 60 | 1001 | 40 18 | 15 01 | 4800 | 0932 | NOAA8 |
| 002 | 60 | 1001 | 40 15 | 15 02 | 13853 | 1634 | |
| 003 | 61 | 1609 | 42 31 | 14 22 | 13867 | 1622 | |
| 004 | 62 | 0438 | 44 22 | 13 47 | 13874 | 0442 | |
| 005 | 62 | 1533 | 45 53 | 13 17 | 13881 | 1610 | |
| 006 | 63 | 0433 | 46 29 | 13 17 | 13888 | 0430 | |
| 007 | 66 | 0506 | 45 46 | 13 08 | 13931 | 0534 | |
| 008 | 66 | 1607 | 45 49 | 13 26 | 13937 | 1522 | |
| 009 | 67 | 1455 | 45 49 | 13 12 | 13951 | 1508 | |
| 010 | 71 | 1603 | 45 41 | 13 01 | 14008 | 1600 | |
| 011 | 72 | 0430 | 45 27 | 13 17 | 14015 | 0420 | |
| 012 | 72 | 1538 | 45 40 | 13 27 | 14022 | 1548 | |
| 013 | 73 | 1515 | 43 27 | 14 18 | 14036 | 1536 | |
| 014 | 74 | 0532 | 43 53 | 14 01 | 14044 | 0536 | |
| 015 | 74 | 1530 | 43 12 | 14 26 | 14050 | 1524 | |
| 016 | 75 | 1515 | 39 59 | 14 49 | 14064 | 1512 | |
| 017 | 76 | 0607 | 40 18 | 14 59 | 14072 | 0512 | |
| 018 | 76 | 1505 | 40 16 | 15 02 | 14079 | 1640 | |
| 019 | 77 | 0439 | 40 10 | 15 10 | 14086 | 0500 | |
| 020 | 78 | 0634 | 40 35 | 14 54 | 14101 | 0628 | |
| 021 | 78 | 0920 | 40 24 | 15 01 | 5056 | 0944 | NOAA8 |
| 022 | 81 | 0820 | 40 53 | 15 01 | 5098 | 0838 | NOAA8 |
| 023 | 81 | 1031 | 40 44 | 15 06 | 5099 | 7018 | NOAA8 |
| 024 | 81 | 1548 | 40 42 | 15 02 | 14149 | 1538 | |
| 025 | 81 | 1952 | 40 54 | 15 04 | 5105 | 2002 | NOAA8 |
| 026 | 82 | 0619 | 40 54 | 15 04 | 14157 | 0540 | |
| 027 | 82 | 0754 | 40 51 | 14 55 | 5112 | 0818 | NOAA8 |
| 028 | 82 | 1527 | 41 03 | 14 44 | 14163 | 1526 | |

Table 8
Special Wind Measurement Runs

| Series | Jday | Time Z Start | End | Comment |
|--------|------|-----------------|------|--|
| a | 64 | 1230 | 1525 | Comparison of Portaloggers 1 & 2 and Northern area toroid while latter still on ship. |
| b | 70 | 1530 | 1600 | Comparison of Portaloggers 1 & 2 and upper and lower anemometers on wheelhouse top. |
| | 71 | 0916 | 0944 | |
| | 71 | 1352 | 1415 | |
| c | 75 | 1628 | 1700 | Horizontal pole in front of ships's bow. Forward anemometer at 4 m. from ship. |
| | 75 | 1941 | 2011 | |
| | 76 | 0925 | 0936 | |
| | 76 | 1013 | 1046 | |
| d | 76 | 1127 | 1207 | As above but forward anemometer at 5m.. |
| e | 76 | 1335 | 1400 | As above, outer anemometer at 4 m. approximately. |
| | 76 | 1847 | 1856 | |
| f | 77 | 1454 | 1624 | Mast mounted vertically in bow. Series ended when Portaloggers damaged - about 0810Z/79. |
| | 77 | 1752 | 1812 | |
| | 77 | 2020 | 2035 | |
| | 78 | 0736 | 0755 | |
| | 78 | 0940 | 1001 | |
| | 78 | 1024 | 1033 | |
| | 78 | 1112 | 1235 | |
| | 78 | 1423 | 1443 | |
| | 78 | 1654 | 1710 | |
| | 79 | 0629 | 0650 | |
| | 79 | 0750 | 0756 | |

Table 9
Shipborne Wave Recorder Runs

| Day No. | Time on | Time off | Comments |
|---------|---------|----------|----------------------------------|
| 64 | 1422 | 1619 | Start roll 1. Steaming. |
| 66 | 0523 | 0543 | Hove to. |
| 66 | 1325 | 1345 | " " |
| 66 | 1940 | 2000 | Steaming |
| 67 | 0718 | 0738 | " |
| 67 | 1509 | 1536 | " |
| 67 | 2100 | 2115 | " |
| 68 | 0537 | 0557 | Start roll 2. Steaming. |
| 68 | 1615 | 1635 | Steaming |
| 68 | 2002 | 2022 | " |
| 69 | 0630 | 0652 | " |
| 69 | 1703 | 1728 | " |
| 69 | 2112 | 2134 | " |
| 70 | 0636 | 0658 | " |
| 70 | 1545 | 1603 | Drifting, CTD yoyo. |
| 70 | 1952 | 2100 | " " " |
| 71 | 1614 | - | Hove to. Ran off end of chart. |
| 72 | 1011 | 1046 | Start roll 3. Hove to. |
| 72 | 1548 | 1630 | Steaming, 5kts. |
| 72 | 1805 | 1825 | Hove to. |
| 73 | 1231 | 1253 | " " |
| 73 | 1947 | 2008 | " " |
| 74 | 0615 | 0635 | " " |
| 74 | 2102 | 2117 | Steaming |
| 79 | 1005 | 1030 | " |
| 80 | 1509 | 1527 | " |
| 81 | 1836 | 1858 | " |
| 81 | 2048 | 2104 | Start roll 4. Hove to. |
| 82 | 0930 | 1030 | Hove to, spar recovery. |
| 83 | 1748 | 1815 | Hove to, CTD. Steaming from 1810 |




Fig.1 Cruise 145 Track Plot




Fig.2. Plan of North Site Sea Soar Survey




Fig. 3. Plan of South Site
SeaSoar Survey




Fig.4 (a) Moorings SOUTHERN SITE




FIG. 4 (b) MOORINGS NORTHERN SITE.




Fig.5 Example of Drifting Spar Rig




Fig.6 CTD stations on Cr 145. Stations labelled 1 to 29 are abbreviations for 11001 to 11029. D=full depth cast.

Y= yoyo




Fig.7 1-minute time series of uncorrected surface met. obs.