

Shipboard Report on Leg 2 of
M S Ferder Shallow Drilling
Programme 1978. May 12 - 26.

Cruise 78/Ferder/05

by

J A Chesher

M Dean

R Holmes

S Brown

CONTENTS

1. Introduction
 2. Personnel
 3. Cruise Results
 4. Geological Results
 5. Equipment Performance
 6. Conclusions and recommendations
-
- Appendix I - Summary Ship's log
- Appendix II - Summary geological borehole logs and site details
-
- Table A - Time analysis
- Table B - Cruise details - graphic
- Table C - Daily operational costs
- Table D - Borehole time and cost analysis
- Table E - Borehole drilling rates
-
- Fig. 1 - Location of borehole sites

Shipboard Report on Leg 2 of m.s.Ferder Shallow Drilling

Programme 1978 - May 12-26

1. Introduction

The purpose of the second leg of the Norwegian drillship m.s. Ferder was to continue the programme of drilling selected priority sites, and if necessary bad weather sites, initiated during the first leg in which pre-Quaternary rocks would be encountered. These sites occur mainly between the north of Lewis and the Shetlands. In addition to the ship's equipment a Fugro designed re-entry system was employed, together with additional wireline drilling equipment provided by Christensen Diamond Products, and a NEC Gas penetration rate meter. A consultant (L. Hill) was contracted to advise IGS on drilling matters.

2. Personnel

J A Chesher	IGS-CSNU	Chief Scientist
M Dean	IGS-CSNU	
R Holmes	IGS-CSNU	
S Brown	IGS-CSNU	
L Hill	Len Hill (Drilling Consultant) Ltd.	

3. Cruise Results

A summary log of operations is presented in Appendix I

and a breakdown time analysis of these operations into steaming, mooring, logging, drilling, port calls, standby, and weather delays is given in Table A. A graphic representation of the cruise details including weather, time analysis, mud consumption and daily costs is given in Table B. A breakdown of the daily costs is given in Table C.

It can be seen from the above data that very little time was lost due to weather but problems with equipment caused a significant period of downtime (see equipment performance).

In total 5 sites were occupied namely:- 78/4 (Site 97); 78/5 (Site 9); 78/6 (Site 18A); 78/7 (Site 17) and 78/8 (Site 66), the location of which are shown in Fig. 1. Borehole 78/6 was not completed due to drilling difficulties. A summary table of borehole time and cost analysis is given in Table D. The limited number of boreholes completed were largely a result of the difficulties encountered drilling particular lithologies and the slow rates of penetration, (see Table E). For future reference graphs showing penetration rate per hour in various lithologies with the particular type of bit used are given in Table E.

4. Geological Results

A summary of the geological borehole logs and site details are given in Appendix II.

Borehole 78/4 situated 9km SE of Stornoway proved the presence

of probable Upper Jurassic shales beneath 55.77m of Quaternary clays. The presence of Jurassic in this area to the west of the postulated position of the Minch Fault, leads support to the conclusion that the Minch Fault is not a continuous line in the Mesozoic in this area downfaulting Jurassic against basement and Permo-Triassic to the west. Instead it follows the coast to downfault the Stornoway beds to the east and is taken up en echelon to the east of Stornoway to downfault the Jurassic against basement.

Borehole 78/5 situated 50km north-west of the Butt of Lewis proved probable Permo-Triassic sandstones beneath 52m of Quaternary boulder clay. As predicted from deep seismic information this confirms the hypothesis that the Mesozoic to the west of the Minch Fault is very thin and the thick Jurassic basin seen in the Minches is no longer present.

Borehole 78/6 was sited to investigate the nature of the Tertiary and underlying Mesozoic to the north-north-west of Cape Wrath. However, due to the difficulty in drilling through the thick surface layer of muddy gravel this site had to be abandoned and borehole 78/7 undertaken in its place to attempt to achieve the same objectives.

Borehole 78/7 sited 85km north-north-west of Cape Wrath proved 84m of Quaternary boulder clay overlying 36m of probable sand. No recovery was obtained in this sand presumed to be the feather edge of the Tertiary. Beneath the sand red and greenish grey mudstones were recovered of presumed Permo-Triassic age. The presence of Permo-Triassic sediments in this region would tend to confirm the absence of late

Mesozoic sediments adjacent to the basement highs.

Borehole 78/8 drilled 4.0m of sand overlying red mottled marls and thin calcareous sandstones of presumed Permo-Triassic age. This borehole proved the continuation of the West Fair Isle basin to the east of the Orkneys.

5. Equipment Performance

Fugro Re-entry system

The re-entry system reached full heave compensation before the drill string and therefore became a limiting factor as to the sea conditions in which it could be used. The guide arms for lowering the bit to the seabed were also too weakly constructed and were continually breaking.

The Fugro system was eventually lost on borehole 78/7 due to the main hoist wire parting. Inspection of the hoist wire showed marked wear for a length of about 10m indicating considerable abrasion perhaps caused by broken bearings in the system. These small bearing would have been better as sheave blocks. Attempts at recovery by fishing down the drillstring failed due to the inability to attach a strong enough hoist wire to the system.

NEC Recorder

The NEC gas rate of penetration and weight of bit meters were of limited value due to difficulty of calibration. The

pen on the penetration meter did not function and negated this part of the equipment. Both parameters given by the NEC recorder were easily obtainable from the driller.

Drilling equipment

Bits

The tungsten carbide bits could not cope with a sufficient variety of lithologies and were continually being changed for other bit types. A heavier duty tungsten carbide bit as was used in the previous year, would have been advantageous but the two on board were incompatible with the new Christensen barrel. The inability to use a pilot bit in the rock roller meant considerable time lost by pulling the string to change to a coring bit. The rates of penetration with different bits in various lithologies are given in Table E.

Barrels

The latching system on the barrels, when fishing caused much delay in that the fist^h would not sink to the bottom to latch onto the inner barrel in the heavy mud used to keep the hole open. The leaf type of latch system also seemed more prone to damage and harder to latch to inner barrel.

The crossover sub to join the rock roller to the drillstring was incompatible. Last year's tungsten bits would also not fit onto the new Christensen outer barrels.

Difficulty was also encountered dropping the push sample tube down the drillstring due to the very close tolerances of the

two pieces of equipment. It was not possible to use the drill string stabilisers since they did not fit through bit guide.

Slips

The ship's slips often failed to hold the drillstring and seemed to require frequent repair. This was considered to be due to the excessive swell present in the area, the failing of the ship's acting, partly as a failsafe arrangement. It was felt that a large part of this problem would not have occurred if the ship had limited its working to only good weather conditions.

Core catchers

The stainless steel IGS core catchers were of insufficient strength to retain core in sandy material, the weight of material caused the catchers to invert and lose the sample.

Gamma Log

The gamma log proved unuseable for the first part of the leg firstly due to a faulty ratemeter dial caused by loose screws and secondly, due to the drive mechanism being inadequately secured to the drive spindle. The amount of wire on the gamma log is excessive for the drum size causing spilling over drum faces and considerable time wastage to disentangle. A power drive to bring the tool up the hole would be advantageous.

6. Conclusions and Recommendations

1. It was obvious that to achieve the objectives at a particular borehole, the site was not always practical in terms of drilling rates, unless one spent a disproportionate amount of time at one site. Future planning should take note of drilling rates and how much time it is reasonable to

allocate to achieve the objectives concerned.

2. The presence of a drilling consultant is probably of value on the first leg and especially in discussions prior to the cruise in relation to the equipment to be used. However, on subsequent legs he often inhibits the drillers' initiative by his presence, and such decisions that are necessary are made by the chief scientist in conjunction with the captain, both of whom have the requisite level of experience.

3. Discussions on drilling equipment and re-entry systems prior to the cruise must be held in the presence of the persons who have the responsibility for using the gear, in this case the captain Hans Jacobsen.

4. Assembly drawings together with complete inventories of equipment must be present on board to save unnecessary searching for gear.

5. Although it was recommended after the previous years work that a good selection of bits to cope with various lithologies encountered should be on board this was not the case this year. Only one type of tungsten carbide bit was available and this produced unacceptably slower drilling rates than the type used in the previous year. The rock roller should have had a pilot roller bit to obviate the necessity for pulling the string and changing the bit to take a core.

A greater number of holes could have been completed had the

drilling rates been faster, and this was the main limiting factor of the cruise.

6. Several instances and time delays were caused by the Christensen equipment not being compatible either with itself or the ship's gear, e.g. the crossover sub to connect the rock roller to the string was the wrong type, the push tube assembly would not easily slide down the string etc. All gear must be checked for compatibility prior to a cruise.

7. Many hours were lost trying to get the latch assembly down the hole in heavy viscous mud to latch onto the inner barrel. This type of leaf latch assembly was undoubtedly inferior to the knob type used in the previous year, when these problems were not encountered.

8. The slips often proved inadequate and failed several times. These should be renewed before use in the future.

9. Telephone communication and telex from ship to shore was often a lengthy and difficult process via Norwegian stations and it was impossible for the shore to reach the ship from Britain. Crystals to enable British stations to be used should be fitted for future use.

10) If anchor loss is chargeable to IGS the wires used should be to IGS satisfaction prior to commencement of charter. The anchor loss on leg 2 could have been prevented if good quality anchor wire had been used.

Not
payable
by
IGS.

- 11) A less archiac gamma logging tool should be purchased.
- 12) The charter of a drill ship should be a complete package and include all drilling facilities, and so avoid the necessity for IGS to become involved in drilling logistics and drilling companies such as Christensen.
- 13) The comment of Dr Evans on Leg 1 that two weeks is too short for a leg was also felt to the case on Leg 2 in that by the time one had become familiarised with the ship and the programme it was time to disembark.
- 14) The NEC gas rate of penetration and weight of bit meters were of limited value, since it proved extremely difficult to calibrate, and anyway both parameters are easily obtainable from the drillers.
- 15) Investigate costs and value of X-raying pipe prior to use to attempt to prevent loss of string by metal failure.
- 16) The Fugro re-entry system was an untested prototype, not compatible with the heave compensation limitations of the ship and reached maximum heave far sooner than the ship. The guide arms were also far too weakly constructed and were continually failing. It would be cheaper for IGS or the owners of Ferder to buy its own re-entry system (estimated cost £5000) rather than to pay the hire rate of £10,000.
- 17) This leg confirmed the suitability of the m.s. Ferder for our shallow drilling programme. In sea states with considerable Atlantic swell the ship was still able to work

*Carried
out.*

satisfactorily.

18) The drilling results of this leg can be considered to be successful. Such delays as were encountered were mainly a direct result of lithological drilling problems that would have to be overcome on any drilling setup.

APPENDIX I

Summary Ship's Log

Friday 12 May

0000-0125 Drilling at 78/3.
0125-0520 Pulled string, diamond bit only 10% worn.
0520-0615 Lifting anchors.
0615-0750 Steaming to site 97 off Stornoway (78/4).
0750-0840 Laying anchors.
0840-1830 Drilling at site 78/4.
1830-1900 IGS crew change: J Chesher, M Dean, R Holmes, S Brown joined ship and D Evans, C Deegan, K Rochow, M Smith disembarked by small fishing boat charge (The Providence).
1900-2400 Drilling rate slowed at ~50m depth, presumed in solid. Continued drilling.

Saturday 13 May

0000-1800 Drilling at site 97.
1800-1820 Fishing vessel bringing gear aboard ship, e.g. radar valves, metal for bit guide etc.
1820-1840 Gamma logging hole, but tool did not function correctly. Ratemeter dial had all screws loose and needle jamming and chart paper could not move whilst winding in probe.
18040-2100 Lifting casing (2100. Fishing boat returned to ship to bring oxygen bottles, not previously delivered from mainland).
2100-2210 Lifting anchors.
2210-2400 Steaming to site 9 (78/5).

Sunday 14 May

0000-0650 Steaming to site 9 (78/5).
0650-0750 Laying anchors and manoeuvring into position.
0750-0815 Lowering re-entry system.
0815-1005 Lowering drill string.
1005-1040 Drilling and sampling at 78/5.
1040-1405 Repairing hydraulics for powerswivel.
1405-1610 Drilling.
1610-1630 Lifting re-entry system from seabed to moonpool due to re-entry system lifting off seabed in swell.
1630-2400 Drilling and sampling.

Monday 15 May

0000-0115 Drilling and sampling.
0115-0155 Lowering re-entry frame.
0155-0345 Pulling pipe to change to diamond bit.
0345-0455 Changing bit.
0455-0900 Running pipe and pulling re-entry system.
0900-2000 Drilling and sampling at 78/5.
2000-2130 Pulling pipe.
2130-2200 Lifting anchors.
2200-2320 Repairing hydraulics to anchor winch.
2320-2400 Lifting anchors.

Tues

Tuesday 16 May

0000-0650 Steaming to site 18A (78/6).
0650-0755 Laying anchors and manoeuvring into position.
0755-0915 Running pipe.
0915-1230 Drilling very slowly - less than 1m in 1 hour.
1230-1320 Lifting pipe to change bit from TC to rock roller.
1320-1735 Manufacturing crossover sub to connect 4½" regular rock roller bit to 4" I.F. drill string.
1735-1900 Running pipe.
1900-1940 Drilling.
1940-2400 Pulling pipe off seabed and waiting on weather. Hole collapsed due to soft muddy gravel.

Wednesday 17 May

0000-0220 Waiting on weather.
0220-0320 Running pipe.
0320-0700 Drilling.
0700-1425 Pulling pipe, difficulties encountered due to hole collapsing and hard to pull out string.
1425-1530 Lifted anchors.
1530-1730 Steaming to site 17 (78/7).
1730-1900 Laying anchors at 78/7.
1900-2115 Running pipe.
2115-2400 Drilling.

Thursday 18 May

0000-0300 Repairing slips on drill floor.
0300-2300 Drilling and sampling.
2300-2400 Difficulty latching fish onto inner barrel.

Friday 19 May

0000-0015 Difficulty with fishing gear.
0015-0130 Drilling and sampling. 0130. Drill string sheared losing 45m of gear consisting of 9 drill collars, 2 drill pipes, 1 inner and 1 outer barrel and 1 TC bit.
0130-0200 Lowering re-entry system.
0200-0440 Pulling pipe, changing bit to rock roller, lowering pipe.
0440-0510 Repairing slips.
0510-0615 Finishing lowering pipe.
0615-1700 Drilling and sampling.
1700-1920 Lowering re-entry system and pulling pipe to change bit due to high torque on string and lack of progress.
1920-2030 Repairing slips.
2030-2400 Lowering pipe and preparing outer barrel. Changed to TC bit.

Saturday 20 May

0000-0845 Drilling and sampling.
0845-1035 Pulling pipe to change to diamond bit due to no progress.
1035-1055 Running string.
1055-1315 Repairing re-entry guide.
1315-1530 Finished running pipe.
1530-2400 Drilling and sampling.

Sunday 21 May

0000-0330 Drilling and sampling.
0330-0425 Repairing drill slips.
0425-1050 Drilling and sampling.
1050-1530 Core barrel stuck in hole, impossible to latch onto inner barrel. This is due to high viscosity of mud necessary to keep hole open preventing latch assembly sinking; or caused by sand backfilling above inner barrel.
1530-2015 Drilling and sampling.
2015-2220 Difficulty connecting fish latch assembly to inner barrel possible due to high viscosity of mud.
2220-2400 Drilling.

Monday 22 May

0000-0825 Drilling and sampling.
0825-0900 Changed piston slips.

0900-0905 Drilling.
0905-1100 Wire of re-entry system parted. Time spent freeing broken wire from drillpipe.
1100-1915 Drilling and sampling.
1915-2015 Attempted logging hole but drive mechanism faulty.
2015-2135 Pulling pipe to 5m above sea bottom to prepare for fishing for re-entry system.
2135-2400 Preparing for fishing for re-entry frame on sea bottom.

Tuesday 23 May

0000-0815 Preparing to fish for re-entry system by threading heavy bar and wire down inside of drill pipe to catch underneath re-entry system.
0815-1730 Pulling remainder of pipe; slow process due to necessity to unthread each pipe from central wire now attached to re-entry system.
1730-1945 Attempted lifting re-entry but proved too heavy and wire broke.
1945-2005 Pulling anchors.
2005 Starboard bow anchor wire broken, lost anchor. Anchor wire was below standard due to rust, as had been commented on previously, and its breaking was not unexpected. IGS should not be deemed responsible for this anchor loss.
2005-2125 Continued lifting anchors.
2125-2400 Steaming to 78/8 (Site 88).

Wednesday 24 May

0000-1030 Steaming to 78/8.
1030-1352 Lowering anchors, delay due to Decca jumping 1 lane.
1352-1515 Preparing and running pipe.
1515-2400 Drilling and sampling.

Thursday 25 May

0000-1340 Drilling and sampling.
1340-1420 Inner core barrel stuck in outer barrel- unable to retrieve.
1420-1530 Pulled pipe.
1530-1700 Lifting anchors.
1700-2400 Steaming to Aberdeen.

Friday 26 May

0000-0600 Steaming to Aberdeen.

0600-0930

Awaiting pilot.

0930-1100

Manoeuvring into Aberdeen Harbour.

1100-2400

In port to change crew and fit McClelland's re-entry system and bring sufficient supply of new drill barrels and coallrs onto deck, to replace those lost on Leg 2.

APPENDIX II

Summary Borehole Logs

Borehole 78/4 (Site 97)

9km SE of Stornoway

Latitude 58°8.6'N Longitude 06°17.6'W

Water Depth 80 metres.

Drift

	<u>Thickness</u>
	<u>m</u>
1. Clay, silty, dark to medium grey, soft becoming firmer towards base. Occasional pebbles present.	52.04
2. Clay, silty, pale reddish-brown with abundant pebbles and large 'gabbroic' pebbles at base.	3.73
UPPER JURASSIC ?	
3. Shale or mudstone, black, fairly soft, with abundant shell fragments and occasional ammonites. Bedding dips at approximately 17½°.	14.28
Total Depth	70.05

Borehole 78/5 (Site 9)

50km NW of Butt of Lewis

Latitude 58°50.55'N Longitude 06°54.7'W

Water Depth 163 metres.

Drift

	<u>Thickness</u>
	<u>m</u>
1. Sand, grey, medium grained, with abundant scaphlopods.	00.30
2. Clay, black, very soft with occasional pebbles.	15.06
3. Clay, pale brown grey with black streaks moderately firm.	5.03
4. Sand ? , no recovery	20.63
5. Clay, sandy, red brown compact with abundant pebbles. Large boulders of hornblende gneiss at base. Boulder Clay?	10.98

	<u>Thickness</u>
	<u>m</u>
PERMO-TRIASSIC?	
6. Sandstones, dark brick red with pale greenish grey reduction patches, fine grained, interbedded with dark brick red slightly micaceous siltstones. Bedding nearly horizontal.	2.50
Total Depth	54.50

Borehole 78/6 (Site 18A)

110km NNW of Cape Wrath

Latitude 59°32.75'N Longitude 5°46.4'W

Water Depth 121m

	<u>Thickness</u>
	<u>m</u>
<u>Drift</u>	
1. Sand, yellowish grey, medium, shelly	0.50
2. Gravel, muddy with well rounded pebbles	6.50

Borehole abandoned due to inability to penetrate muddy gravel

Total Depth 7.0

Borehole 78/7 (Site 17)

85km NNW of Cape Wrath

Latitude 59°20.57'N Longitude 5°35.45'W

Water Depth 104m

	<u>Thickness</u>
	<u>m</u>
<u>Drift</u>	
1. Mud, gravelly, sandy with shell fragments	10.00
2. Clay, sandy, grey brown with frequent metamorphic pebbles.	74.00

TERTIARY?

3. No recovery, possible sand	36.00
-------------------------------	-------

PERMO-TRIASSIC?

4. Mudstone, silty, red and grey green, soft, micaceous with thin white lenses. Bedding dips at 10°.	7.78
--	------

Total Depth 127.78


Borehole 78/8 (Site 88)


21km ESE of Ronaldsay

Latitude 58°44.75'N Longitude 2°35.8'W

Water Depth 74 metres.

	<u>Thickness</u> <u>m</u>
<u>Drift</u>	
1. Sand, olive grey, shelly, medium-coarse grained	3.90
PERMO-TRIASSIC?	
2. Mudstones and siltstones, brick red with green reduction spots, with thin interbedded red calcareous micaceous sandstones	10.74
Total Depth	14.64





I. G. S. EDINBURGH/M. S. FERDER OPERATIONS - ESTIMATED RUNNING COSTS IN £000'S STERLING

DESCRIPTION OF EXPENDITURE 1978	DAY No.	1	2	3	4	5	6	7	TOTAL FOR THE WEEK ENDING	TOTAL C/F CUMULATV. WEEK ENDING
	DATE: Br. Fwd.	Mon.	Tues.	Wed.	Thur.	Fri.	Sat.	Sun.	7.5.78	7.5.78
HIRE OF M.S. FERDER AS A UNIT		2.499	4.000	4.000	4.000	7.000	7.000	7.000	35.505	35.505
RENTAL STINGRAY FR. & COMPEN.		1.820	.160	.160	.160	.160	.160	.160	2.780	2.780
RENTAL CHRISTENSEN EQUIPMENT		1.625	1.625	1.625	1.625	1.625	1.625	1.625	11.375	11.375
RENTAL SAFETY JT. & FISHING TAP		.044	.044	.044	.044	.044	.044	.044	.308	.308
MUD & CHEMICALS		Nil	Nil	.823	.411	1.646	1.908	1.640	6.428	6.428
DIAMOND/ROCK BITS		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
CONSUMABLE SPARES		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
SUB CONTRACTORS COSTS PERSONNEL		.352	.352	.352	.352	.352	.352	.352	2.464	2.464
COST OF MESSING		.028	.028	.028	.028	.028	.028	.028	.196	.196
NEC Gas Equipment ROP/WOB		1.020	.020	.020	.020	.020	.020	.020	.240	.240
TOTAL DAILY COST		6.488	6.229	7.052	6.640	10.875	11.137	10.869	59.296	
TOTAL CUMULATIVE COST B/F		6.488	12.717	19.769	26.409	37.284	48.421	59.296	59.296	
TOTAL CUMULATIVE COST DAILY		6.488	12.717	19.769	26.409	37.284	48.421	59.296	59.296	59.296



TABLE C

I. G. S. EDINBURGH/M. S. FERDER OPERATIONS - ESTIMATED RUNNING COSTS IN £000's STERLING

DESCRIPTION OF EXPENDITURE 1978	DAY NO.	DATE:							I4	TOTAL FOR THE WEEK ENDING	TOTAL C/ CUMULATV WEEK ENDING
		8	9	10	11	12	13	14			
	Br. Fwd.	Mon.	Tues.	Wed.	Thur.	Fri.	Sat.	Sun.	14.5.78	14.5.78	
HIRE OF M.S. FERDER AS A UNIT	35.505	7.000	7.000	7.000	7.000	7.000	7.000	7.000	49.000	84.505	
RENTAL STINGRAY FR. & COMPEN.	2.780	.160	.160	.160	.160	.160	.160	.160	1.120	3.900	
RENTAL CHRISTENSEN EQUIPMENT	11.375	1.625	1.625	1.625	1.625	1.625	1.625	1.625	11.375	22.750	
RENTAL SAFETY JT. & FISHING TAP	.308	.044	.044	.044	.044	.044	.044	.044	.308	.616	
MUD & CHEMICALS	6.428	1.586	.613	Nil	.014	.367	Nil	.367	2.947	9.375	
DIAMOND/ROCK BITS	Nil	Nil	Nil	7.000	Nil	Nil	Nil	Nil	7.000	7.000	
CONSUMABLE SPARES	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	
SUB CONTRACTORS COSTS PERSONNEL	2.464	.352	.352	.176	.176	.176	.176	.176	1.760	4.224	
COST OF MESSING 2.Christensen left 10.5.78	.196	.032	.032	.023	.023	.023	.023	.023	.188	.384	
NEC Gas Equipment ROP/WOB Recor	.240	.020	.020	.020	.020	.020	.020	.020	.140	.380	
Weather Forecasts & Telephone	.022	.022	.022	.022	.022	.022	.022	.022	.154	.176	
TOTAL DAILY COST		10.841	9.868	9.255	16.084	9.437	9.070	9.437	73.992		
TOTAL CUMULATIVE COST B/S	59.296	70.137	80.005	89.260	105.344	114.781	123.851	133.288			
TOTAL CUMULATIVE COST DAILY		70.137	80.005	89.260	105.344	114.781	123.851	133.288		133.288	

TABLE C

I. G. S. EDINBURGH/M. S. FERDER OPERATIONS - ESTIMATED RUNNING COSTS IN 1000's STERLING

DESCRIPTION OF EXPENDITURE 1978	DAY No.	15	16	17	18	19	20	21	TOTAL FOR THE WEEK ENDING	TOTAL CUMULATIVE WEEK ENDING
		DATE: Br. Fwd.	DATE: Tues.	DATE: Wed.	DATE: Thur.	DATE: Fri.	DATE: Sat.	DATE: Sun.		
HIRE OF M. S. FERDER AS A UNIT	84.505	7.000	7.000	7.000	7.000	7.000	7.000	7.000	49.000	133.505
RENTAL STINGRAY FR. & COMPEN.	3.900	.160	.160	.160	.160	.160	.160	.160	1.120	5.020
RENTAL CHRISTENSEN EQUIPMENT	22.750	1.625	1.625	1.625	1.625	1.625	1.625	1.625	11.375	34.125
RENTAL SAFETY JT. & FISHING TAP	.616	.044	.044	.044	.044	.044	.044	.044	.308	.924
MUD & CHEMICALS	9.375	2.555	3.824	.403	2.536	2.620	2.169			
Diamond Pilot Insert £500 DIAMOND/ROCK BITS £400 R.C. BIT £128	7.000	.500	.400	.120	N11	N11	N11	N11	1.020	8.020
Lost in BH78/7 1.5m CB & Inner Barrel 8.0m 1.5m 8.0m 1.5m 8.0m 1.5m	N11	N11	N11	.300	N11	12.320	N11	N11	12.620	12.620
SUB CONTRACTORS COSTS PERSONNEL	4.244	.176	.176	.176	.176	.176	.176	.176	1.232	5.476
COST OF MESSING	.384	.023	.023	.023	.023	.023	.023	.023	.151	.535
Mec Gas ROP & WOB Recorders	.380	.020	.020	.020	.020	.020	.020	.020	.140	.520
Weather Forecasts & Phone	.176	.022	.022	.022	.022	.022	.022	.022	.154	.530
TOTAL DAILY COST		12.125	13.394	9.893	11.606	24.010		11.233		
TOTAL CUMULATIVE COST B/F	133.288	145.413	158.707	168.707	180.313	204.323	215.556			
TOTAL CUMULATIVE COST DAILY		145.413	158.707	168.707	180.313	204.323	215.556			


I. G. S. EDINBURGH/M. S. FERDER OPERATIONS - ESTIMATED RUNNING COSTS IN 1000's STERLING

DESCRIPTION OF EXPENDITURE 1978	DAY NO.	DATE:	Br. Fwd.	24	23	24	25	26	27	28	TOTAL FOR THE WEEK ENDING	TOTAL C/ CUMULATV WEEK ENDING
				Mon.	Tues.	Wed.	Thur.	Fri.	Sat.	Sun.		
HIRE OF M.S. FERDER AS A UNIT	133	505	7000	7000	7000	7000	7000	7000	7000	7000	49000	182505
RENTAL STINGRAY FR. & COMPEN.	5	020	100	100								
RENTAL CHRISTENSEN EQUIPMENT	34	125	1.625	1.625	1.625	1.625	1.625	1.625	1.625	1.625	11375	45500
RENTAL SAFETY JT. & FISHING TAP	9	24	044	044	044	044	044	044	044	044	308	1232
MUD & CHEMICALS	26	165	1.865	360	NIL	708		NIL				
DIAMOND/ROCK BITS	8	020	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL		
CONSUMABLE SPARES, T.C. PLOT	12	620	NIL	NIL	150	050	050	050	NIL	4		
SUB CONTRACTORS COSTS PERSONNEL	5	476	176	176	176	176	176	176				
COST OF MESSING	5	545	023	023	023	023	023	023				
NIC	5	20	020	020	020	020	020	020	020	020	140	660
WT + PROXC	3	330	022	022	022	022	022	022	022	022	154	484
TOTAL DAILY COST			10935	9430	9060	9658	8960					
TOTAL CUMULATIVE COST B/F	217	208	258143	247573	256633	266301	275261					
TOTAL CUMULATIVE COST DAILY			238143	247573	256633	266301	275261					

Borehole No

SITE NO	97	9	8A	17	88
WATER DEPTH	0.80 m	c 163 m	121 m	10 km	7 km
TOTAL TIME ON SITE (DAYS)	Wed 37.2 hrs (12-00)	13 Weds. 4 hrs (14-15)	Wed 32.5 hrs (16-17)	6 days 148 hrs (12-23)	Wed 24 hrs (24-25)
TIME MOORING & RAISING	2.0 hrs	1.75 hrs	2.1 hrs	3.2 hrs	
TOTAL DEPTH	70.5 meters	54.5 meters	7.0 meters	127.78 m	14.64 m
THICKNESS QUATERNARY	55.77 m	52.00 m	7.0 m	84.0 m	3.90 m
QUATERNARY LITHOLOGY	22m soft grey clay 32m red brown pebbly clay	41.02m soft grey clay 10.98m red brown pebbly clay	7.0m Muddy ground	80m Sandstone 7.8m Ironstone 7.8m Red marl	Sand shaly
THICKNESS SOLID	14.28 m	2.50 m		43.78 m	10.76 m
SOLID LITHOLOGY (AGE)	14m Black Ugnissile	2.5m Red sandstone formation		360m Test sand? 7.8m Ironstone 7.8m Red marl	
RECOVERY QUATERNARY	28.78m = 51.2%	15.08m = 29%	2.0m = 28.6%	9.44m = 11.2%	1.0m = 25.6%
RECOVERY SOLID	7.95m = 55.7%	1.52m = 60.8%		5.88m = 13.4%	1.78m = 16%
TOTAL RECOVERY	36.73m = 52.1%	16.60m = 30.0%	2.0m = 28.6%	15.32m = 11.9%	2.78m = 19%
SALT GEL	2.4 meters	16.2 meters	23.0 meters	75.5 meters	
SIF		250 kg	1025 kg	175 kg	
MUD - LIME	60 kg	380 kg	40 kg	2340 kg	
BARYTE		200 kg	650 kg	450 kg	
LOTHER					
MUD COST	\$367.60	\$3222	\$4227	\$12,223	
BIT USAGE					

78/FERDER/05 - DRILLING RATES BORE HOLE 78/4



Jurassic shales/mudstones


Tangy red pebbly fill

Flandrian soft grey clay

TC BIT

TIME IN HOURS


78/FERDER/05 - DRILLING RATES BOREHOLE 78/S.



BOREHOLE NO 78/S.

LITHOLOGY	AGE	THICKNESS	DRILLING TIME HRS	DRILLING RATE m/h	BIT
Soft grey clay	Flandrian	20	4	5	TC
Loose sand	Quaternary	20	4 1/2	4.4	TC
Tough red fill pebbly Boulder clay	Quaternary	10	3 1/2	2.9	TC
Sandstone cobbles	Quaternary	1	3	0.3	TC
Gneiss boulder	Quaternary	2	2	1	Diam
Sandstone silt	Permo-Triassic	2 1/2	7	0.35	Diam

78/FERDER/DS - DRILLING RATES
 BORE HOLE 78/6



N.B. Hole collapsed after each run
 Penetration remaining on rock roller
 wire when pulling pipe to change
 had to TC bit hole would collapse.


Collapsed hole caused problems extracting pipe from Trestles.

BOREHOLE 78/6

LITHOLOGY	AGE	THICKNESS	DRILLING TIME HRS	DRILLING RATE 1/L	R.T.
MUDY GRAVEL	QUAT	5	3 1/2	1.4	TC
MUDY GRAVEL	QUAT	2	2	1.0	Rock Roller
MUDY GRAVEL	QUAT	7	8	0.9	Rock Roller

78/FORGER/D5 - DRILLING RATES
BORE HOLE 78/D

PENETRATION
IN METRES



REAR GREEN SILTY CLAYS

SAND

CLAY PEBBLES
DIA NOM 80
QUARTZITE BOULDERS
IN CLAY

LITHOLOGY	AGE	THICKNESS	DRILLING (HR)	PULLING RATE (M/L)	BIT
Hard Gravel (Run)	QUAT	10	4 1/2	2.2	TC
" " (Run?)	"	10	1	10	Rock Roller
Clay pebbles (Run)	"	5.7	3 1/2	4.3	TC
" " (Run?)	"	5.7	1.2	4.8	Rock Roller
Quartzite clay (Run)	"	3	2	1.5	TC
Quartzite (clay Run)	"	5	5	1.0	Rock Roller
Quartzite silty (Run)	"	5	3	1.7	Diamond
Clay pebbles (Run?)	"	14	14	1.0	Diamond
Sand?	(Run?) TGP?	30	5	6	Diamond
Reddish clay (Run?)	?	7	15	2.1	Diamond

20 22 24 26 28
TIME IN HOURS

78/FERDER/05 - DRILLING RATES. BOREHOLE 78/8

LITHOLOGY	AGE	THICKNESS	DRILLING TIME HRS	DRILLING RATE M/L	BIT
Sand	Q.uit	6.0	1	6.0	TC
Red mottled siltstones & mudstones	Permian-Triassic	11.0	35	0.3	TC

PENETRATION

IN METERS

20



0 2 4 6 8 10 12 14 16 18 20 22 24 26 28 30 32 34 36 38 40 42 44 46 48